

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
FW20	001	2008	Chevy	SLV 2500	4C	TRK	June	4WD, Engine: 6 liter V8, AC, Automatic, power doors and windows, no cap	202507	Y	1GCHK29K78E202507	Light Blue	173,183		Poor - see attached DMV inspection
PS1	002	2012	Ford	Fusion	4dr	Auto		4 cyl, 2.5L engine, Auto, A/C, Power Steering, power mirrors and seats.	380848	Y	3FAHP0GA7CR380848	White	120,983		Exhaust leak, rear brakes are squeaking.
FW15	003	2015	chev	1500 SLV	4C	trk		Totaled, 15,000 in damage	267225	Y	1GCVKPEC8FZ267225		Est: 75,000		Totaled, 15,000 est for repair, salvage title
AOT10	004	2011	Chevy	CHEV	TRK	TRK		CHEVY 1500 5.3L AUTO 4X4	256526	AOT sending	1GCRKSE32BZ256526	Black	102,197		Severe front end damage Hood wont open Tires are bald Seats not bolted down Back windows smashed out Front of bed smashed Frame bent, salvage title
PS1	005	2011	Ford	C/V	4dr	Auto		8 cyl. 4.6 liter engine, Police Interceptor, Auto, A/C, Power Steering, power mirrors and seats.	146414	Y	2FABP7BV9BX146414	Green	114,003		Body damage/Exh Leak/struts leak.
FPR8	006	2009	Toyota	Matrix	4H	Auto	April 2018	4 door toyota matrix, front wheel drive, automatic trans, 4 cylinder, aftermarket bluetooth	026021	Y	2T1KU40E09C026021	Blue	133,873		Good condition - no known issues.
FPR8	007	2010	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01858B111	Green			Good - working condition - replaced with new
FPR8	008	2011	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01513G911	Green			Good - working condition - replaced with new
FPR8	009	2011	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01525G911	Green			Good - working condition - replaced with new
FPR8	010		Paddle Ki	PK2000		boat		Paddle boat: aluminum dual pontoon paddle boat, capacity- 4 adults, chain driven paddle wheel			PAB01834B111	Silver			very good. These units are being sold because the drive chain will come off the drive sprocket. Not suitable for park rental use. Damage to steering handle
FPR8	011		Paddle Ki	PK2000		boat		Paddle boat: aluminum dual pontoon paddle boat, capacity- 4 adults, chain driven paddle wheel			PAB01526G911	Silver			very good. These units are being sold because the drive chain will come off the drive sprocket. Not suitable for park rental use. Some damage to steering handle
FPR8	012		Paddle Ki	PK2000		boat		Paddle boat: aluminum dual pontoon paddle boat, capacity- 4 adults, chain driven paddle wheel			PAB01514G911	Silver			very good. These units are being sold because the drive chain will come off the drive sprocket. Not suitable for park rental use. Some damage to steering handle
FPR8	013		Paddle Ki	PK2000		boat		Paddle boat: aluminum dual pontoon paddle boat, capacity- 4 adults, chain driven paddle wheel			PAB01860B111	Silver			very good. These units are being sold because the drive chain will come off the drive sprocket. Not suitable for park rental use. Some damage to steering handle
FPR8	014		Paddle Ki	PK2000		boat		Paddle boat: aluminum dual pontoon paddle boat, capacity- 4 adults, chain driven paddle wheel			PAB01839B111	Silver			very good. These units are being sold because the drive chain will come off the drive sprocket. Not suitable for park rental use. Some damage to steering handle
FPR8	015		Paddle Ki	PK2000		boat		Paddle boat: aluminum dual pontoon paddle boat, capacity- 4 adults, chain driven paddle wheel			PAB01515G911	Silver			very good. These units are being sold because the drive chain will come off the drive sprocket. Not suitable for park rental use. Some damage to steering handle
FPR8	016		Paddle Ki	PK2000		boat		Paddle boat: aluminum dual pontoon paddle boat, capacity- 4 adults, chain driven paddle wheel			PAB01516G911	Silver			very good. These units are being sold because the drive chain will come off the drive sprocket. Not suitable for park rental use. Some damage to steering handle

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
FPR8	017	2011	Paddle Ki	PK3000	RAFFLE - \$1 TICKETS SOLD BY STATE SURPLUS PROPERTY ON 5/11/18 FROM 11:00 am -3:00 pm AND 5/12/18 FROM 8:00 am -10:00 am TICKETS SOLD AT THE AUCTION SITE ONLY			Paddle boat: Aluminum pontoon Paddleboat 12' two person -		DRAWING WILL BE HELD JUST PRIOR TO AUCTIONING OFF THE PADDLE BOATS - MUST BE ON-SITE TO WIN	PAB01524G911	Blue			RAFFLE ITEM: Good - working condition - replaced with new
FPR8	018	2011	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01512G911	Green			Good - working condition - replaced with new
FPR8	019	2011	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01518G911	Red			Needs minor repair - replaced with new
FPR8	020	2011	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01508G911	Blue			Needs minor repair - replaced with new
FPR8	021	2010	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01836B11	Green			Needs minor repair - replaced with new
FPR8	022	2011	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01507G911	Blue			Good - working condition - replaced with new
FPR8	023	2011	Paddle Ki	PK3000				Paddle boat: Aluminum pontoon Paddleboat 12' two person			PAB01520G911	Red			Good - working condition - replaced with new
BGS56	024							TIRES Pallet 1 = (2)225/60R16-Cooper WeatherMaster S/T 2 (2 Tires)-10/32,(2)225/60R16-Goodyear Integrity 97S (2 Tires)-10/32,(4)205/55R16-Cooper CS5 Grand Touring 91T-1@7/32 1@8/32 2@9/32,(4)205/55R16-Cooper CS5 Grand Touring 91T-8/32(4)205/60R16-Cooper ST/2-8/32,(4)215/55R16-Hankook Winter I Pike RS 97T-1@9/32 2@10/32 1@11/32,(4)225/60R16-Cooper CS5 Grand Touring 98T-1@9/32 3@10/32,(4)225/60R16-Cooper LifeLiner GLS 98T-1@5/32 2@7/32 1@8/32							Used - tread depth is included in description (see x/32)
BGS56	025							TIRES Pallet 2 = (2)225/50R17-Uniroyal Tiger Paw (2 Tires)-9/32,(2)225/60R17-Cooper LifeLiner Touring SLE 99T (2 Tires)-1@6/32 1@7/32,(4)225/50R17-Michelin Energy Saver A/S 93V-7/32(4)225/50R17-Michelin Energy Saver A/S 93V-8/32,(4)225/50R17-Michelin Energy Saver A/S 93V-8/32,(4)225/60R17-Cooper CS4 Touring 99T-2@7/32 2@8/32,(4)225/65R17-Toyo Open Country A20-2 @ 6/32 1 @ 7/32 1 @ 9/32,							Used - tread depth is included in description (see x/32)

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
BGS56	026							TIRES Pallet 3 = (1)215/55R16-General Altimax Arctic (1 Tire)-10/32,(1)225/60R16-Firestone FR710 97T (1 Tire)-6/32,(2)225/65R17-Bridgestone Dueler HP Sport AS (2 Tires)-1@7/32 1@8/32,(2)265/70R17-Hankook I-Pike RW11 (2 Tires)-1@8/32 1@10/32,(3)225/60R17-Sumitomo Touring LST 99T (3 Tires)-6/32,(4)205/60R16-Goodyear Assurance-2 @ 6/32 1 @ 7/32 1 @ 8/32,(4)265/70R17-Hankook I-Pike RW11 115T-1@2/32 1@4/32 1@6/32 1@7/32,(4)265/70R17-Hankook I-Pike RW11 115T-2@6/32 2@8/32							Used - tread depth is included in description (see x/32)
BGS56	027							TIRES Pallet 4 = (4)265/70R17-Bridgestone Dueler AT RHS-12/32,(4)265/70R17-Goodyear Wrangler Fortitude HT RWL 115T-10/32,(4)P265/70R17-Michelin LTX A/T2 RWL 113S-12/32							Used - tread depth is included in description (see x/32)
BGS56	028							TIRES Pallet 5 = (4)205/55R16-Michelin Primacy MXV4 89H-9/32,(4)215/55R16-Continental ContiProContact 97H-10/32,(4)215/55R16-Continental ContiProContact 93H-1@7/32 3@8/32,(4)215/55R16-Hankook Winter I-Pike RS-1@6/32 3@7/32,(4)215/60R16-Goodyear Assurance-1@8/32 3@9/32,(4)LT245/75R16-Bridgestone V-Steel RIB 265 120/116S-1@8/32 1@9/32 2@13/32							Used - tread depth is included in description (see x/32)
BGS56	029							TIRES Pallet 6 = (2)195/65R15-Yokohama Avid S33B (2 Tires)-6/32,(4)185/60R15-Cooper WeatherMaster S/T 2-10/32,(4)185/65R15-Cooper CS4 Touring-3 @ 9/32 1 @ 11/32,(4)185/65R15-WestLake Radial RP18-3@8/32 1@7/32,(4)195/60R15-Fuzion Touring-2@5/32 2@8/32,(4)195/65R15-Yokohama Avid S33B 89H-9/32,(4)195/65R15-Yokohama Avid S33B 89H-8/32							Used - tread depth is included in description (see x/32)
BGS56	030							TIRES Pallet 7 = (4)215/55R17-Goodyear Assurance 94V-7/32,(4)225/60R16-Goodyear Integrity 97S-9/32,(4)255/70R17-Bridgestone Dueler H/T 684II 110S-9/32,(4)215/55R17-Goodyear Assurance 94V-7/32							Used - tread depth is included in description (see x/32)

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
BGS56	031							TIRES Pallet 8 = (2)245/75R16-Dunlop GrandTrek (2 Tires)-9/32,(4)215/60R16-Goodyear Assurance 95H-10/32,(4)205/60R16-Goodyear Assurance 95H-3@8/32 1@9/32,(4)215/55R17-Goodyear Assurance-8/32,(4)225/65R17-Toyo Open Country A20 101H-2 @ 6/32 2 @ 7/32							Used - tread depth is included in description (see x/32)
AOT14	032							Sander frame: Hopper Sander Sander Sub Frame home made.							Rusty
FPR8	033	1997	Honda	TRX400	ATV			Honda Foreman 395cc 4x4. 5 speed.	224571	N/A	478TE2004VA224571	Green	1,601	1022	Good. Runs well. Some cosmetic damage.
FPR8	034	2013	John Deer	X540	riding mower			Mower: 54" mower, 26hp 4 cycle liquide cooled engine,variable speed hydrstatic transmission,			1M0X0540JDM082074	Green		509	rough shape / mower deck has seized pullys / battery is dead, number 4055
FPR8	035	2014	John Deer	X540	riding mower			Mower: 54" mower, 26hp 4 cycle liquide cooled engine,variable speed hydrstatic transmission,			1M0X540AKEM090283	Green		715.7	runs descent /descent shape / battry is dead, number 4015
FPR8	036	2003?	Polaris	GEM E825	LSV			Electric low speed vehicle. 2 passenger. Cargo box.	026662	N/A	5ASAG27492F026662	Yellow	UNK	UNK	Poor. Does not run. Needs new batteries.
FPR8	037	1989	The Brute	105-26				wood splitter / Honda 11hp engine / 4 way split wedge	261536	N/A	88-105-26-1536				hydraulic tank leaks
FPR8	038	2000	John Deer	F935	Riding Mower			Mower: Front end lawn mower. Diesel. 72" deck.			M0F935X186450	Green		1510	Fair to poor. Bearing box on PTO shaft needs work.
FW19	039	2002	Kubota	G2460G	riding lawn mower		NA	Mower - Kubota riding lawn mower with 60" mowing deck. Rear wheel 2WD. Gas-powered. 24hp. Electric power steering. Hydrostatic transmission.			11407	Orange	NA	704	sometimes machine won't start before and after use; other times it starts just fine. Reverse doesn't work. Power steering issues that needs recalibrating or new \$900 part. Aside from these issues, it still mows grass.
FW10	040	1999	Honda	Fourtrax 300		manual		ATV - engine malfunction	016052	N/A	478TE1506XA016052				runs, engine issues
AOT10	041	2000	Wain Roy					Bucket: Wain Roy Ditching Bucket off of 110 JD Excavator							
AOT10	042	2000	Wain Roy					Bucket: Wain Roy Digging Bucket off of 110 JD Excavator							
AOT10	043		Jeraco					Cap Truck: Fiberglass Truck Cap							
FPR8	044		MichiCraft					Canoe: Aluminum Canoe			T123H102				Has damaged keel - floats, no known leaks, older model replaced with new
FPR8	045		Perception	Prodigy 10				Kayak: 10' Single Kayak.				Red			Cosmetic scratches and dents. May have minor leak.
FPR8	046	2010	Perception	Acadia ii				Kayak: Tandem Kayak			WEMDGXHM010	Yellow			fair - patched end but does not leak
FPR8	047		Perception	Prodigy 10.0				Kayak: 10' Single Kayak.				Red			Cosmetic scratches and dents. May have minor leak. Missing foot rest assembly.
FPR8	048		Walden	Voyageur				Kayak: 10' Single Kayak.			s/n: WHQ42937E404	Yellow			Cosmetic scratches and dents.
FPR8	049		Walden	Voyageur				Kayak: 10' Single Kayak.			s/n: WHQ42583D404	Yellow			Cosmetic scratches and dents. May have minor leak.
FPR8	050	2013	Perception	Prodigy				Kayak: Single Kayak			WEMTRACUG313	Red			Good - no leaks, seat torn - replaced with new
FPR8	051		Perception	Prodigy 10				Kayak: 10' Single Kayak.				Orange			Cosmetic scratches and dents. May have minor leak. Missing foot rest assembly.
FPR8	052		Perception	Sparky 9.5				Kayak: 9.5' Single Kayak.				Green			Cosmetic scratches and dents.
FPR8	053		Walden	Voyageur				Kayak: 10' Single Kayak.			s/n: WHQ42926E404	Green			Cosmetic scratches and dents. May have minor leak.
FPR8	054		kayak					Kayak: perception swift 3.1 / single kayak			WEMEXPC2D606	Red			leaks
FPR8	055		kayak					Kayak: perception swift 3.1 / single kayak			WEMEXPBVD606	Red			leaks

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
FPR8	056		kayak					Kayak: perception swifty/ single kayak			wemtrd6fnf010	Red			leaks
FPR8	057		Great Canadian					Kayak: Single Kayak			No S/N	Orange			fair -old due for replacement - no foot pegs doesn't leak.
FPR8	058	2013	Perception	Prodigy				Kayak: Single Kayak			WEMTRACTG313	Red			good - no leaks, side padding torn - replaced with new
FW11	059A	1996	Shorlander		Trailer		Oct 22	Pontoon Boat Trailer	772547	N/A	1MDBUP12XTF772547	White			Fair
FW11	059B	1996	Sylvan		Boat			24 ft. pontoon boat	82H596	N/A	SYL41582H596	White			Fair
FW11	059C	1995	Evinrude	E60TELD	outboard			60 hp 2 cycle outboard engine		N/A	Ser. # G03951924	Blue			Fair
FW15	060	2002	PAS	PAS10S		TRAILER	N/A	Snowmobile trailer- 101"X10'	389669	Y	1P9BS10182W389669				Structural issues with frame.
FW10	061	1983	MERCUR	Version M	Outboard			Motor: 18 HP - Outboard Motor			9348239	Black/Blue		Unknown	Fair / Runs
FW10	062	1979-'85?	MERCUR	MERC110	Outboard			Motor: 9.8 HP - Outboard Motor			VIN Tag Missing	Black/Red		Unknown	Fair
FPR8	063		Bourdon I	Basic Bunk Model				2 Each Bed: Basic metal framed bunk beds - 30X76 mattresses							Good - replaced because top bunk lacked side rails
AOT36	064							Chain Tire: 12 Used Misc. sizes, Truck Tire chains							
AOT36	065		JD					Bucket: Cutting Edges for JD 544E Loader							New
AOT10	066		Reading	Classic II	Tool Box			Body Truck: Reading Truck Body							RF Door dented, Scratched up
AOT10	067		Napa					Jack: 3 1/2 ton Floor Jacks							Needs work Inop.
AOT10	068		Omega					Jack: 22 Ton Air JACK							Needs work, Inop.
AOT10	069		AFF					Jack: 22 Ton Air JACK							Needs work, Inop.
AOT36	070							Jack: 10 Ton Floor Jack							Works needs TLC
AOT10	071		Hobart	R300				Welder: Stick Welder 208/230/460V.			78WS05508	Blue			No Known Defects
FPR8	072		Rockwell	12-RAS				Saw: 1.3HP Radial Arm Saw.			s/n: JS4428				Runs. Unknown condition.
AOT10	073		MSA	Orion				10 Each: Meter: Multi Gas Meter							Need Calibration and possibly Batteries (2)AOT10, AOT14, AOT17, AOT19, AOT27, (2)AOT31, AOT34, AOT36
FPR8	074	2003	Kenwood	TK2100				8 Each Radio: Hand held protalk portable two way radio. Two channel 2 mile range. Includes 2 batteries and charger			50100669				Fair - works fine - replaced with new
AOT10	075							Cones: 34 Traffic Cones				Orange			No Known Defects
AOT10	076		Bed locke	BL2004				Bed Cover: 8' Pick up truck bed cover, Electric							Missing Paint. May not work?
AOT10	077	2012	Lift Moor	Crane				Crane truck mount style: 6500 Truck mounted crane 12VElect/Hyd							Electrical Contacts defective in rotator
AOT36	078							Winch: 1000Lbs Elect. Winch with Hyd. Manual hoist for trailer or truck mounting.							New
AOT36	079							Winch: 1000Lbs Elect. Winch with Hyd. Manual hoist for trailer or truck mounting.							New
FPR8	080		Miller	Bobcat 225G				Welder: AC/DC welder and 8000 watt generator.			s/n: KC212497	Blue			Fair. Needs new battery and a tune-up.
BGS43	081		CJ BEAM					Stabilizing jack: for trailer with 4 plates							Fair condition - working when removed from service
BGS43	082		Friedrich	WS10B10				Air Conditioner: 10000 btu							New in box, through wall mount - never installed
BGS43	083		Despatch	LAC1-38B-2				Oven lab: Digitronic lab oven, 240 volts							Used, good condition, NO KNOWN DEFECTS
BGS43	084		Kwik-Way					Valve Refacer: Kwik-way							Used, excellent condition

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
BGS43	085							Bulbs and Ballasts: pallet of 100 plus HID bulbs and ballasts - various sizes, styles, and watts							New, never used
AOT10	086							Parts: Misc. Parts,							
BGS56	087	2009	Chevy	Express 3500	Van	Auto	8/31/2018	RWD 6.0L V8 Auto Trans AM/FM Cruise Control Power locks and windows AC	116983	Y	1GAHG39K291116983	White	80411		Mechanical - Service stabilitrac light on; Front end shimmy when braking. Body - Right rear door corner trim loose; Trim over right rear lamp broken & inside van; Paint peeling in rear wheel wells; Dents in left side rocker panels; Paint peeling from door sills; Stone chips on hood; Paint bubbling on front edge of hood; Dents in rear doors; Paint peeling around rear door handle; Scratches & paint chips along right side; Wheels rusting Interior- rear trim panels loose, missing, off, in rear of van; Driver's door weatherseal loose at bottom; Front side door weatherseal loose at bottom; Tear in driver's seat; Tears in upholstery on rear seats; Holes in trim from radio removal; Driver's seat belt difficult to buckle & unbuckle.
FPR8	088	2002	chevy	3500 SLV	dp	trk		silverado 3500, 3500 1 ton with 3yd dump body /8.1 vortec engine / electric dump body / standard transmission	255145	N/A	1GBJC34G72E255145	Green	102520		runs descent / body rust / needs a new clutch
PS1	089	2011	Chev	Caprice	4dr	Auto		8 cyl. 6.0 liter engine, Police package, auto, a/c, power steering, power mirrors and seats.	550963	Y	6G1MK5E22BL550963	Green	136767		Brakes Rusty, Check engine light on, code: PO322
FPR8	090	1997	Chevrolet	3500	PK	TRK	2/18	Automatic. 2WD. Regular Cab. Stake Bed with Dump.	044949	N/A	1GBHC34R2VE044949	Green	72777		Fair. Possible leak in rear fuel tank. Rust and cosmetic damage. Steering issues.
FPR8	091	2005	CHEVY	2500 HD	PK	TRK		silverado 2500HD, 3/4 ton HD 2500 / 6.0L vortec engine / automatic transmission / 96" Astoria STD Service Body	297629	FMS sending	1GBHC24U45E297629				high mileage / runs rough / odometer does not work / brake light on / check engine light on, fiberglass utility box
AOT10	092	2009	Chevy	1500 SLV	CW	TRK		2009 Chevy 1500 5.3L Auto 4WD 3.73R	265579	Y	3GCEK23389G265579	Black	102495		Motor Smokes,Ck eng. Lamp on,TPMS light on.
LIQ1	093	2011	Chevy	Tahoe	4W	Auto	12-18	4DR,4WD,AUTO,ELEC LOCKS & WINDOWS, V8	361334	Y	1GNSK2E05BR361334	Black	136449		Good. No know mechanical defects.
BGS56	094	2011	Ford	EPD	4W	Auto	6/30/2016	4WD 5.4L V8 Auto Trans AM/FM Single CD Cruise Control Power locks, windows, mirrors and seats AC	F36761	Y	1FMJU1G56BEF36761	Blue	59499		Mechanical - TPMS Light On. Unable to road test due to expired state inspection. End user reported no known defects prior to turning vehicle in. Body - Paint wearing from driver's door sill; Dent and scrape on passenger door; Scratches along both sides; Small dent in left front fender; Stone chips on hood; Rear wiper motor weak. Interior - Upholstery lightly stained.
BGS56	095	2011	Ford	Focus	4DR	Auto	2/28/2018	FWD 2.0L 4Cyl Auto Trans AM/FM Single CD Cruise Control Power locks, windows and mirrors AC	127710	Y	1FAHP3FN5BW127710	Green	70005		Mechanical - Unknown - Unable to road test. End user reported no known defects prior to turning vehicle in. Body - Scratches on left rear bumper; Scratches on left side doors; Stone chips on hood & front bumper; Left side rocker panel rusting. Interior - Upholstery lightly stained.

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
PS1	096	2011	Ford	Fusion	4 Dr.	Auto		4 cyl, 2.5L engine, Auto, A/C, Power Steering, power mirrors and seats.	243500	Y	3FAHP0GA8BR243500	White	118,969		Rusted rocker panel passenger side.
BGS56	097	2011	Ford	Focus	4dr	Auto	4/30/2018	FWD 2.0L 4Cyl Auto Trans AM/FM Single CD Cruise Control Power locks, windows and mirrors AC	127714	Y	1FAHP3FN2BW127714	Green	66473		Mechanical - Appears mechanically sound with no known defects. Body - Scratches along left side; Scrape on left rear bumper; Small dents in roof; Scratches on roof; Scratches on hood; Scrapes & small gouge in front bumper; Stone chips on hood; Right side windshield washer nozzle missing; Scratches on right front fender; Rocker panels rusting; Rust on bottom edge of left rear door. Interior - Upholstery lightly stained.
PS1	098	2012	Chev	Equinox	4W	Auto		4WD, 6 cyl, 3.0L engine, Auto, A/C, Power Steering, Power mirrors, and seats.	247156	Y	2GNFLEE56C6247156	Silver	133827		NKD
BGS56	099	2011	Ford	Focus	4Dr	Auto	4/30/2018	FWD 2.0L 4Cyl Auto Trans AM/FM Single CD Cruise Control Power locks, windows and mirrors AC	182158	Y	1FAHP3FN9BW182158	Blue	84907		Mechanical - Rotational noise in front end while driving. Body - Scratches on left side doors; Scratches on right rear door; Right rear mud flap missing; Stone chips & dents in hood. Interior - Upholstery lightly stained.
PS1	100	2011	Chev	Traverse-LS	4W	Auto		AWD-6 cyl. 3.6 liter engine, Auto, A/C, Power Steering, power mirrors and seats.	337424	Y	1GNKVEED4BJ337424	Gray	129921		NKD
PS1	101	2010	Chev	Malibu	4dr	Auto		4 cyl. 2.4 liter engine, Auto, A/C, Power Steering, power mirrors and seats.	190463	Y	1G1ZC5EB4AF190463	Gold	111644		Tire light on, light body damage to driver side rear corner/ light rust
PS1	102	2011	Ford	Fusion	4dr	Auto		4 cyl, 2.5L engine, Auto, A/C, Power Steering, power mirrors and seats.	269034	Y	3FAHP0GA3BR269034	Silver	117093		NKD
PS1	103	2007	CHEV	TK, SLV	4C	TRK		8 cyl.4.8 liter engine, Auto, A/C, Power Steering, power mirrors, and seats	591929	Y	1GCEK19C87Z591929	Red	98778		Tire light on, right side manifold bolt broke, right side little rusty and rear fenders
PS1	104	2008	Chev	Tahoe-LS	4W	Auto		4WD, 8 cyl., 5.3L engine, Auto, A/C, power steering, power mirrors, power door locks, power windows, power seats.	238745	Y	1GNFK03018R238745	Green	135607		Exhaust leak, rust on left rear.
BGS56	105	2009	Chevy	Express 3500	Van	Auto	12/31/2017	RWD 6.0L V8 Auto Trans AM/FM Cruise Control Power locks, windows and mirrors AC	172768	Y	1GBHG39K991172768	White	55782		Mechanical - TPMS light on; Unable to road test - Inspection expired. Body - Paint peeling from upper passenger side doors; Trailer plug hanging by wires; Dents in rear bumper; Paint peeling from rear doors; Scratches on left side panel; Paint peeling on top corners of front fenders; Stone chips on hood; Scratches along right side; Paint peeling along top left side. Interior - Holes in trim from radio removal; Paint wearing from all door sills; Interior trim panels torn, loose, missing; Rearmost seat missing; Upholstery badly stained; Passenger door lower weatherseal loose.

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
BGS56	106	2013	Chevy	Express 3500	UT	VAN	8/31/2018	RWD 6.0L V8 Auto Trans AM/FM Cruise Control Power locks, windows and mirrors AC	157286	Y	1GAZGZFG9D1157286	Green	85069		Mechanical - TPMS light stays on. Body - Scratches on right front fender; Rear seat missing; Scratches & dents in rear doors; Dents in rear bumper; Scratches on driver's door; Scratches on front bumper; Scratches on hood; Paint wearing from door sills; Front side door window will not close - latch screws missing; Driver's door seal taped in place; Driver's mirror glass broken; Rust on rear bumper. Interior - Tears in rear seats; Small holes in front seat upholstery; Holes in trim from radio removal; Trim paint stained.
PS1	107	2009	Toyota	RAV4	4W	Auto		4X4, 4 cyl, 2.5L engine, Auto, A/C, Power Steering, power mirrors and seats, 4 Dr.	013075	Y	JTMBF33V695013075	Silver	101,476		Exhaust Leak, Brakes rusty
AOT10	108	2011	Chevy	2500 SLV	4C	TRK		2011 CHEVY 2500HD 6.0L AUTO 4X4	365026	Y	1GC2KXCG6BZ365026	Black	148382		No Known Defects
LIQ1	109	2011	Chevy	Tahoe	4W	Auto	4-18	4DR,4WD,AUTO,ELEC LOCKS & WINDOWS, V8	361003	Y	1GNSK2E04BR361003	Black	116195		Good. No know mechanical defects.
AOT10	110	2011	Chevy	2500	SV	Van		Chevy Express 2500 6.0l AUTO VAN	134871	Y	1GNZGYFG7B1134871	Orange	98569		Seats missing for rear, Hole in Left rocker panel,Rear brakes dragging,Hole in plastic bumper,Tires cupped,Interior not assembled.
BGS56	111	2011	Ford	Fusion	4DR	Auto	10/31/2018	FWD 2.5L 4Cyl Auto Trans AM/FM Single CD Cruise Control Power locks, windows and mirrors AC,	346154	Y	3FAHP0GA4BR346154	Silver	85690		Mechanical - Appears mechanically sound with no known defects. Body - Small scrape on right rear bumper cover; Scratches on right rear quarter; Scratches on trunk lid; Scratches on left rear quarter; Scratches on left rear door; Stone chips on hood; Small scrape on front bumper cover. Interior - Upholstery moderately stained.
LIQ1	112	2013	Ford	XPL	UT	Auto	2-18	4DR,4WD,AUTOELEC LOCKS AND WINDOWS, V6	B79118	Y	1FM5K8ARXDGB79118	Black	116629		Good. No know mechanical defects.
BGS56	113	2014	Jeep	Patriot	UT	Auto	8/31/2018	4WD 2.4L 4Cyl Auto Trans AM/FM Single CD Cruise Control Power locks, windows and mirrors	598486	Y	1C4NJRBB6ED598486	White	122740		Mechanical - Appears mechanically sound with no known defects. Body - Holes in roof from light bar removal; Scratch on right rear fender; Paint peeling from driver's door sill; Left front & both rear mud flaps missing; Dent & paint chips on left front fender; Stone chips on hood & grille. Interior - Upholstery stained & worn; Does not heat well.
AOT10	114	2008	IH	7600	CC	TRK		2008 INTER7600 CUMMINS ISM11L FULLER10SPD	697114	Y	1HTWXahr78J697114	Orange	135190	6636	Does not like to Regen, Dump body has holes,
AOT10	115	2008	IH	7600	CC	TRK		2008 INTER 7600 CAT C13 FULLER 10SPD	697116	Y	1HTWXSBR88J697116	Orange	145,611	7701	Misc lights out,Left front brake can bad,Hyd. Tank leaking, Glad hand broken,Valve cover leaking,Oil pan bad,Coolant leak,Trans out put shaft seal leak,Dump body prop bad.
AOT10	116	2007	IH	7500	CC	TRK		2007 INTER 7500 INT/570 AL/3000RDS6-SP	461351	Y	1HTWLazr87J461351	Orange	117658	6320	Oil Pan Rusty and leaking around oil pan plug, Valve cover gasket leaking, King pins loose, Using coolant.
AOT10	117	1993	FORD	L8000	Tractor	TRK		Fifth Wheel, Tractor, M8SPD Cummins 300HP	A19744	N/A	1FDYW82E7PVA19744	Green	26213	607	No Known Defects
AOT10	118	2008	IH	7600	CC	TRK		Right hand wing, 2008 INTER7600 CUMMINS ISM11L FULLER10SPD	697114	Y	1HTWXahr28J697114	Orange	105,878	5342	Misc. Hyd. Oil leaks, Rust holes in body

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
AOT10	119	2008	IH	7600	CC	TRK		2008 INTER7600 CUMMINS ISM11L FULLER10SPD, Left hand wing, Rev. Plow.	697107	Y	1HTWXahr58J697107	Orange	125,552	6110	Left convex mirror broken, Rear body hole in it, Inner body equalizer valve leaking hyd.,Rear wing shelf arm remote broken,Epation tank small coolant leak, Eng. Brake inop.
AOT10	120	2007	IH	7400	CC	TRK		RH Wing, 570 Allison Auto	461321	Y	1HTWLAZR7J461321	Orange	120,869	5238	RH Mirror Bezel cracked, Body Tender,AC InOP,Tail Gate Cyl Leaks, Muffler Hanger Broken,
AOT10	121	2006	IH	7400	CC	DUMP TRK		RH Wing, 570 Allison Auto	344718	Y	1HTWLAZR26J344718	Orange	171,377	7344	Wing cracked, Body tender, Tarp ripped and bent, Pinion seal leakng,Muffler hanger broken, RH power steering box leaking
AOT10	122	2014	IH	TerraStar	DMP	TRK		2014 INTER TERRASTAR MAXFORCE 7 AUTO 4X4, Crew Cab, Reversible plow, Stainless Galleon Body, 8 CYL.	042665	Y	1HTKPSKK4EH042665	Blue	50219	1974	Regen issue, Motor back fires and fills cab with smoke a couple times a day,
AOT14	123	2004						Hot Box: Oil Fired Hot Box 12 years old	603166	AOT sending	T40012603166				Burner issues
AOT14	124	2005	AMER	TL	UT			Message Board & Trailer	228019	Y	1A9BS333552228019				Most of the Pixels are out
AOT10	125							Bed Truck: 12' Steel Flat bed for Truck							
AOT10	126	2008	IH	7400	CC	TRK		Left hand wing, 2008 INTER 7400 570/MAXFORCE10 AL/3000RDS	696913	Y	1HTWDAZR68J696913	Orange	55496	4710	Misc. Hyd. Oil leaks, Rust holes in body
AOT10	127	2008	INTL	7600	CC	TRK		2005 INTER 7600	697103	Y	1HTWXahr88J697103	Orange	133720	6211	Cylinder Head Gasket Oil Leak, Rusty
AOT10	128	2007	IH	7500DP	CC	TRK		RH Wing, 570 Allison Auto	461322	Y	1HTWLAZR17J461322	Orange	109656	5355	Fan belt Cracked, Bed chain gear box leaks, Hole in exhaust pipe, Wing hose leaks, Mis. Lights out, Tarp arm bent, Air comp. leaks oil, Power steering Reservoir leaks, RH steer tire worn.
AOT10	129	2007	IH	7500	CC	TRK		Right hand wing, 2007 INTER 7500 INT/570 AL/3000RDS6-SP	461320	Y	1HTWLAZR87J461320	Orange	125679	6940	Hyd. Leak, Wing coupler bracket broken, Wing spot out,RF fender lamp out,Hyd. Level low, Plow marker lamp out.
AOT10	130	2000	JD	544H	LOADER			John Deere 544H Loader	577536	N/A	DW544HX577536	Yellow		6272	Exhaust Pipe from muffler to Stack broken, Left Front axle seal leaking,Misc. oil leaks, Bucket broken, Articulating Pins loose, Boom Pins loose, Misc. Hydraulic Leaks
DMV6	131	2004	Felling	Utility Tilt	SC			16' Scale trailer,Hyd. Tilt,7000Lbs with 12v Winch	021375	Y	5FTUH162541021375	Black			Fair, Some rust, no ID plate
DMV6	132	2004	Felling	Utility Tilt	FB			16' Scale trailer,Hyd. Tilt,7000Lbs with 12v Winch	021374	Y	5FTUH162341021374	Black			Fair, Some rust
NS483-ORG	133	1992	JD	TK	EX		N/A	EXCAVATOR	532615	N/A	DW690DR532615	Green		2721	GOOD
NS483-ORG	134	1999	INTL	TK	CC	TRK	06/18	DUMP TRUCK WITH SLIDE IN SANDER	653005	Y	1HTSDAAR9XH653005	Red	132679	11246	SOME RUST
NS483-ORG	135	2002	INTL	TK	DP	TRK	08/18	DUMP TRUCK WITH SLIDE IN SANDER, PLOW, WING	550897	Y	1HTMNAAM22H550897	Red	74174	5958	SOME RUST
NS516	136	1995	INTL	4900	DP	TRK	10/18	4x2 Plow Truck, plow and tailgate sander, 466 DT Engine, New 6 speed transmission (Jan 2018), Air brakes, New exhaust brake (Jan 2018), New oil pan (Oct 2017), new kingpins (Oct 2017), new power steering box (Oct 2017), new fuel tank (Oct 2017), repaired windshield wiper motor and arm, 3 new bearing and chain on tailgate sander	651323	Y	1HTSDAAR1SH651323	Red	67878	7256	Cab firewall needs rust repair, hydraulic pump needs work, dump body needs some repair and paint, runs and drives well, needs TLC, traction control air line leaking, plow needs TLC

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	Title status	Complete VIN#	Color	Mileage	Hours	Condition
AOT10	137	2005	IH	7500	DMP	TRK		2005 INTER 7500 INT/570 FUL/10SPDM	158739	Y	1HTWLAZR25J158739	Orange	111366	6210	Check Eng. Lamp on,ABS light on,Oil cooler water pipe bad,Turbo oil drain tube bad,Exhaust pipe bad and flex,Air tank cables bad,Bed chain worn,Dump body piston leak,Rear tires worn,Turbo oil supply bad,Mirror Pass side broken,Cracked wing, Valve cover Injector harness bad.
AOT10	138	2006	IH	7400	CC	DUMP TRK		Right hand wing,2006 INTER 7500 INT/570 AL/3000	344720	Y	1HTWLAZR06J344720	Orange	108600	5957	Tarp assembly missing, Muffler leaks and hanger broken, Coolant leak rear of engine
AOT10	139	2007	IH	7500	999	TRK		2007 INTER 7500 INT/570 FUL/10SPD	461364	Y	1HTWLAZR67J461364	Orange	100889	5582	Plow Piston leaking,Misc. lights out,Exhaust stack rotted,L Mirror cover cracked,Gear box leaks,Frt body Hyd hose leaking at crimp.
AOT10	140	2007	IH	7500	CC	TRK		2007 INTER 7500 INT/570 AL/3000RDS6-SP	461358	Y	1HTWLAZR07J461358	Orange	140560	6759	Misc. Light s oiut, ABS light on, Plow in poor condition, Wing in Very poor condition.
AOT10	141	2008	IH	7600	CC	TRK		2008 INTER 7600 CAT C13 FULLER 10SPD	697117	Y	1HTWXSBRX8J697117	Orange	171788	8691	Air leak secondary,Drivers seat ripped,Rear body towers rotted,Body rotted,Misc lights out,Trailer plug broken,Hyd leak inner body equilizer valve,Tarp arms broken,Tarp in opt.,Engine oil leak,Front plow lever sticks,Marker switch broken,Drivers doror handle rotted.
AOT10	142	1978	Certified	Tank		TRAILER		1978 CERTIFIED TANDEM TANK TRAILER, Fifth Wheel	382735	N/A	9382735		59,518		Cross members and sub frame rusted, Wont pass Inspection