

MAY 13, 2023 LIVE AUCTION. LIST SUBJECT TO CHANGE.

Division	LOT#	Year	Make	Model	Body	Auto/Trk	Auto/Trk	Description	last 6 VIN	title	Complete VIN#	Color	Mileage	Hours	Condition
AOT10	1							PALLET OF PIPETTES LIQUID ANALYZERS		NA					New
AOT10	2							PALLETS OF MIXED VIKING TUB BODY PARTS BEARINGS, CHAINS, CYLINDERS, SPROCKETS		NA					New, Not installed
AOT10	3							PALLETS OF MIXED VIKING TUB BODY PARTS BEARINGS, CHAINS, CYLINDERS, SPROCKETS		NA					New, Not installed
AOT10	4							PALLETS OF MIXED VIKING TUB BODY PARTS BEARINGS, CHAINS, CYLINDERS, SPROCKETS		NA					New, Not installed
AOT181	5							PALLET OF MIXED INTERIOR AND EXTERIOR VEHICLE AND HOME LIGHTING		NA					Unknown Condition
AOT181	6							PALLET OF MIXED LIGHT BOXES FOR STREET LIGHTS		NA					Unknown Condition
AOT181	7							PALLET OF MIXED ELECTRICAL TOOLS, DRILLS, BATTERIES		NA					Unknown Condition
AOT10	8							ELECTRICAL COMPONENTS / MOTORS		NA					Unknown Condition
AOT10	9							PALLET OF INTERNATIONAL TRUCK STAINLESS OIL PANS		NA					New, Not installed
AOT10	10							PALLET OF MIXED SURVEYING EQUIPMENT		NA					Unknown Condition
AOT10	11							PALLET OF MISC. PAINT SUPPLIES/SPRAY PAINT		NA					Unknown Condition
AOT181	12							PALLET OF MIXED SAFETY GEAR		NA					
AOT10	13							PALLET OF STARTERS AND ALTERNATORS		NA					
AOT181	14							PALLET OF DIM MARKERS AND SIGN ROLL		NA					
AOT10	15							PALLET OF MIXED FILTERS, AIR / OIL / HYDR		NA					
AOT10	16							PALLET OF OEM GM PARTS		NA					New, Not installed
AOT10	17							PALLET OF (3) VIKING TUB BODY MAILHOT HOIST CYLINDERS		NA					New, Not installed
AOT10	18							PALLETS OF MIXED VIKING TUB BODY PARTS BEARINGS, CHAINS, CYLINDERS, SPROCKETS		NA					New, Not installed
AOT181	19							PALLET OF (2) PUMPS		NA					Unknown Condition
FPR8	20	unknown	Wilderness Systems	Pamlico 1451	Kayak			Wilderness tandem kayak		NA	N/A	Orange			no obvious defects, most likely has holes that create leaks when in water, has been left outside for about two years
FPR8	21	unknown	Perception	N/A	Kayak			Perception landem kayak		NA	N/A	Yellow			one broken seat, comes with detached seat back, most likely has holes that create leaks when in water, has been left outside for about two years
FPR8	22	unknown	Perception	Sparky	Kayak			Perception single kayak 9.5 feet		NA	N/A	Green			no obvious defects, most likely has holes that create leaks when in water, has been left outside for about two years
AOT10	23							(8) GOODYEAR WRANGLER TIRES SIZE 275/65/18		NA					Take-Offs, Low Miles
AOT10	24							(8) GOODYEAR WRANGLER TIRES SIZE 275/65/18		NA					Take-Offs, Low Miles
AOT10	25				B107J107C107:G107A107:G107			(4) GOODYEAR WRANGLER TIRES SIZE 275/65/18 & (4) GOODYEAR WINTER COMMAND 225/65/17 & (3) GOODYEAR WRANGLER FORTITUDE 255/65/17		NA					Take-Offs, Low Miles
AOT10	26							(4) COOPER DISCOVERER SRX TIRES SIZE 235/70/16		NA					Take-Offs, Low Miles
BGS43	27							4 Cooper Discoverer R16 205/55, 4 Cooper Weathermaster Studded R17 225/65		NA					USED
FPR8	28		Husqvarna	GCV160				push mower		NA					Used property in good condition, but considerable repairs required.
FPR8	29		Craftsman					push mower 163CC		NA					Used property in good condition, but considerable repairs required.
FPR8	30	2009	John Deere	Gator HPX 4x4	UTV			Gator HPX 4x4, gas UTV, 2WD/4WD side by side	070154	NO	1JDUV41B99M070154	Green	n/a	1472.4	<b>BOS Only</b> , old but runs well, ripped seat
PS19	31	2014	Alcom	10' EXTREME	FLAT SNOW			Sno Pro Trailer - 2 place flatbed snowmobile trailer with electrical	038958	COO	5WFBS1014EW038958	Aluminum	n/a	n/a	Good
PS19	32	1997	Hydra Sports	200CEAN	Boat			21', 200 hp Evinrude engine (unknown hours), 1997 EZ Loader trailer.	05D797	MSO	HSX9020SD797boat/D797HY97trailer	White	unknown	1114	Unknown. No title for trailer
PS19	33	2006	Yamaha	LF250TXR	n/a	n/a		250 HP outboard motor with rigging	005415	NA	1005415	Gray		1700	Running
FPR8	34							Traveller 12V DC Winch 4500lb capacity		NA	2272650378				fair condition and usable without repairs
FPR8	35	2013	John Deere	X540	Mower			2013 John Deere X540 riding mower with 54" deck.		NA	1MXS40AADM082057	Green		742.8	cracked front cover, missing chute and potentially other parts, seat broken and detached from mower -- cannot be driven due to safety in seat, but does start
FPR8	36	2012	Cub Cadet	XT3 Enduro	Mower			2012 Cub Cadet XT3 Enduro riding mower with 54" deck		NA	E266H7007	Yellow		unknown	mower has low compression, does not start, potentially missing parts
FPR8	37		Paddle King					Pedal Boat	17G911	NO	PAB0151TG911				Used property in good condition, but considerable repairs required.
FPR8	38	2014	Kawasaki	KAF620PEF				Mule 4000	503884	TC?	JK1AFCP11EB503884	Red		1456	good condition with considerable use left before any important repairs would be required.
FPR8	39	2012	Kawasaki	KAF620PCF	UTILITY			Mule 4000	502606	COO	JK1AFCP15CB502606	Green		1112	good condition with considerable use left before any important repairs would be required.
FPR8	40	2013	John Deere	X540	Mower			2013 John Deere X540 riding mower with 54" deck		NA	1MXS40AADM082060	Green		unknown	front left tire damaged and unusable, disconnected front end, missing chute and potentially other parts, cannot be driven
AOT10	41		Kay					Pedal Boat		NA		Yellow			Used property in good condition, but considerable repairs required.
FPR8	42		Kay					Pedal Boat		NA	KAX06327E004	Blue			Used property in good condition, but considerable repairs required.
FPR8	43		Kay					Pedal Boat	16H707	NO	KAX07016H707	Green			Used property in good condition, but considerable repairs required.
FPR8	44	2016	Gem	eM1400 LSV	UTV			2WD UTV 2 seater with bed	005849	COO	52cu2nafnq3005849	white/black			electric, does not run
FPR8	45		John Deere	X590				mower	122111	NA	1MXS90EVAHM122111			803	good condition with considerable use left before any important repairs would be required.
FPR8	46		John Deere	X590				mower		NA	1MXS90ELHM122127			478	fair condition and usable without repairs
FPR8	47		Club Car		golf cart			golf cart		NA	Serial number AQ0931-038893	GREEN			does not run, bottom rusted out, no Key
FW20	48	2000	John Deere	LT155				riding lawn mower	092598	NA	MOL155B092598	green	n/a	unknown	Missing motor mounts, needs a new bumper, head gasket, deck belt, and overall tune-up, no key. Dealer quoted \$1400 last year.
TBD	49	2013	SKIDOO	GT SPORT		FW0113		SNOWMOBILE 600ACE ENGINE	000475	NO	2BPSETDAXDV000475	BLACK/GRAY			<b>BOS Only</b>
TBD	50	2013	POLARIS	136 LXT TURBO		FW0111		LXT TURBO	000086	COO	SN1PTT7S9EC000086	BLACK/GRAY			
FW15	51	2007	Ski Doo	SM LEGEND TOURING	SNOWMOBILE			V-800 - 4 stroke	000200	COO	2BPSKB7AV000200	Gray	798		Fair
							330 Magnum 4x4 ATV								
TBD	52		POLARIS	A05CD32AA	ATV-05 MAG330 SILVER				025163	NO	C04025163	UNK	UNK		<b>BOS Only</b> , UNKNOWN CONDITION
FW15	53	2005	POLARIS	A05CD32AA	ATV-05 MAG330 SILVER				686967	COO	4XACD32A55B686967	Grey	UNK	UNK	Poor - no KEY
FW15	54	2014	POLARIS	S14PT6HSL	SNOW-14 600 IQ LXT			330 Magnum 4x4 ATV	005818	COO	SN1PT6HSECO05818	Black	3600	UNK	Good
FW15	55	2005	POLARIS	A05CD32AC	ATV-05 MAG330 MO NEWBRKUP			330 Magnum 4x4 ATV	683436	COO	4XACD32A35B683436	Camo	UNK	UNK	Fair
FW15	56	2005	POLARIS	A05CD32AB	ATV-05 MAG330 SPTSMN			330 Magnum 4x4 ATV	678583	COO	4XACD32A25B678583	Green	UNK	UNK	Fair
FW15	57	2005	POLARIS	A05CD32AC	ATV-05 MAG 330 MO NEWBRKUP	ATV	N/A	Sportsman 330 Magnum 4X4	683351	COO	4XACD32A65B683351	CAMO	1415	N/A	NOT RUNNING
FW15	58	2005	POLARIS	A05CD32AC	ATV-05 MAG 330 MO NEWBRKUP	ATV	N/A	Sportsman 330 Magnum 4X4	675069	COO	4XACD32A65B675069	CAMO	1163	N/A	NOT RUNNING
FPR8	59	2016	POLARIS	GEM EM1400 LSV	LSV/NEV			2016 Gem Car em 1400LSV (street legal, low-speed vehicle), electric UTV	005848	COO	52CU2NAF8G3005848	White	6977		parking brake has been removed, no batteries comes with it, worn but runs well
AOT 10	60							OVERHEAD CRANE 5 TONS - SHEPPARD NILES		NA					
AOT181	61							GENERATOR, SKID - ONAN GENSET, NO BATTERY		NA					
AOT31	62							HOT WATER PRESSURE WASHER AMERICAN		NA					
AOT10	63							WILTON BANDSAW		NA					
AOT10	64							BOBCAT SKIDSTEER CLAMSHELL BUKET		NA	AEN003346				
AOT10	65							AIR COMPRESSOR QUINCY MODEL		NA					
TBD	66		SKIDOO					SM LEGENDS TOURING	000205	COO	2BPSKB7AX7V000205	GRAY	3830		
FW15	67	2008	Arctic Cat	550 EFI		ATV		4 Wheeler/Needs Battery	206450	NA	4UP09ATV89T206450	Black			<b>BOS Only</b>
FW11	68	2000	Polaris	Indy Xtra				Snowmobile	003933	NO	4XAST5BS4XC003933	Blue	3934		<b>BOS Only</b> , Fair
AOT181	69							LANDA PRESSURE WASHER							
FW15	70	2009	Brunswick	150GDA	15' Boat			15' Boston Whaler Gaurdian Boat w/ below trailer	341809	MSO	WCG000341809	White		172.9	Good
FW15	71	2008	Boatmaster	BCG15AGUS-25	Trailer			Boat MasterTrailer	112974	COO	42XBG15157H112974				Good
AOT181	72							~15' aluminum boat		NA					
AOT10	73							TRUCK MOUNTED DRILL RIG		NA					Used, minor leaks, working condition, no known defects.
AOT181	74							woodsplitter - low behind		NA					
AOT10	74							PAIR OF 8' SCALES OFF TRAILER WITH WINCH'S AND READERS		NA	0805AF105** *(17-20)				Used, working condition
BGS56	75	2016	SUBA	IMP	SW	Auto	10/2023	Impreza, Sedan AWD, AWD 2.0L 4 Cyl Pwr windows, locks, mirrors AC AM/FM/CD Cruise Control USB Ports	274442	YES	JF1GPA061G8274442	Blue	117,928		<b>Mechanical:</b> Had to jump start vehicle, will probably need battery, transmission gear selector shifts hard, exhaust heat shield rattles, brakes were frozen from sitting, brakes are rusty and pulsate, vehicle has been sitting a few months awaiting disposal, tires are winter tread with approx 50-75% tread life remaining, one owner vehicle purchased new, selling due to normal rotation of inventory. <b>Body:</b> Both rear rocker panels on both sides are rusted heavily, left rear door damage, right rear bumper scrapes, lower front bumper scratched, stone and rust chips on hood and roof, some other minor scrapes. <b>Interior:</b> Interior was recently detailed, equipped with all weather floor liners.
BGS56	76	2013	SUBA	IMP	4D	Auto	12/2022	Impreza, 4 dr sedan, AWD 2.0L 4 Cyl Pwr windows, locks, mirrors AC AM/FM/CD USB Ports	019824	YES	JF1GJAA65DH019824	Silver	83,850		<b>Mechanical:</b> AWD Equipped, vehicle has been sitting for a few months awaiting disposal, tires are winter tread with about 75% tread life remaining, last user reported no known issues or defects, selling due to normal rotation of inventory. <b>Body:</b> minor scrapes throughout, rear rocker panels starting to rust, few minor door dings <b>Interior:</b> Interior is dirty and in need of cleaning, all weather floor liners.
BGS56	77	2014	SUBA	IMP	4D	Auto	8/2022	Impreza, Sedan, AWD 2.0L 4 Cyl Pwr windows, locks, mirrors AC AM/FM/CD Cruise Control USB Ports	019556	YES	JF1GJAB66EH019556	Gray	103,906		<b>Mechanical:</b> Vehicle was in use up until the VT State inspection expired Feb 2023, will not pass VSI without bodywork at a minimum, unknown other mechanical issues <b>Interior:</b> Interior in fair shape, needs cleaning <b>Body:</b> Rust, rot, scrapes, dents
BGS56	78	2014	FORD	FOC	4D	Auto	02/2023	Focus, Sedan, 2.0L 4 cyl, AM/FM/CD PW, PL, PM, cruise,	238764	YES	1FADP3F2XEL238764	Grey	73,391		

																		Mechanical: Estimated \$3,500 - \$4,500 in repairs needed, DIAGNOSED WITH NO POWER TO PCM, WIRE HARNESS FROM FRAME TO PCM CORRODED AND BROKEN, REPAIRED WIRE HOWEVER THE PCM AND ONE OF THE TIPM CONNECTORS LOCKS ARE BROKEN AND SHOULD BE REPLACED. \$3,500 repair at least, not considering other repairs needed to pass VSI. <b>Body:</b> Scratches, dings, minor rust throughout <b>Interior:</b> interior is dirty and in need of cleaning
BGS56 FPR8	79 80	2016 2011	DODG FORD	CVN TK	SV PC	Auto TRK	11/2023 08/23	Grand Caravan . 3.6L 6 cyl. AM/FM/CD PW, PL, PM, cruise, 2WD Ford Ranger	383190 A55555	YES YES	2C4RDGBG5GR383190 1FTKR1ED7BPA55555	Black White	81,723 40893					Fair
LIQ1	81	2019	FORD	XPL	UT	AUTO/TRK	08/2023	Police pursuit vehicle. SUV, AWD, Auto Trans, Electric Locks windows and Drivers seat. New brakes, and wheel bearings.	B18351	YES	1FM5K8AR1KBG18351	Red	91528					front end body damage. Collision with a deer. Sheet metal and bumper grill assembly damage. Air bag deployment. Vehiles runs. Strong clean car.
EC8	82	2007	TOYT	MTX	4H	AUTO	4/30/23	Matrix. Studded Snow Tires with less than 1,000 miles, power windows, power door locks, 2WD, 4 cylinder engine, auto, hatchback, A/C, CD player and AM/FM radio, remote locks	671093	YES	2T1KR32E97C671093	Gray	145,947					Rust on right rear rocker panel, front break rotors rusted, rear heat shields detached, broken glove box hatch, no hub caps
BGS56	83	2014	HOND	CIV	4D	Auto	12/2022	Civic Hybrid. 1.5L 4Cyl AC AM/FM CD Pwr windows locks mirrors Cruise control	000510	YES	19XFB4726EE000510	BLUE	101,994					<b>Mechanical:</b> Estimated repairs needed \$3,500-\$5,000, vehicle is leaking brake fluid under dash, dealership diagnosed vehicle as needing a new brake master cylinder, tires are winter tread with 50-75% tread life remaining, had to jump start vehicle for condition report, may need engine start battery, last user reported no known issues other than what is stated, car does run and drive providing the brake fluid is kept topped off. <b>Body:</b> Some rust starting on front hood, minor scratches may be found throughout, some rust starting on front hood, minor scratches throughout, <b>Interior:</b> Interior lightly stained
BGS56	84	2017	SUBA	OUT	UT	Auto	2/2023	Outback. 4WD 2.5L 4Cyl AC AM/FM CD Pwr windows locks mirrors Cruise Control	429173	YES	4S4BSAAC5H3429173	Silver	89,814					<b>Mechanical:</b> tires are winter tread with approx 50% tread life remaining, equipped with rubber all weather floor liners, last user reported no known issues up until accident. Vehicle runs and drives on lot. <b>Body:</b> Right front accident damage from a deer collision, minor scratches throughout. <b>Interior:</b> Interior is dirty, some accident debres in rear of vehicle.
BGS56	85	2012	DODG	CVN	SV	Auto	2/2023	Grand Caravan. Van. 3.6L 6 Cyl Pwr windows, locks, mirrors AC AM/FM/CD Cruise Control	203628	YES	2C4RDGBG6CR203628	Black	78,736					<b>Mechanical:</b> Vermont state inspection expired February 2023, will not pass VSI again without rust repairs at a minimum, had to jump start vehicle for condition report, van has been sitting a few months in preparation for sale, last user reported no known issues or defects, tires are winter tread with approx 50-75% tread life remaining. <b>Body:</b> Will not pass VT state inspection without some rust repairs performed, there's rust along the lower edges of doors and lower body areas, minor scratches may be found throughout, headlights are hazy, paint starting to bubble on front hood. <b>Interior:</b> Interior equipped with stow-n-go fold into the floor seating, carpeted interior, interior is fairly clean, no tears, stains or major odors noticed.
BGS56	86	2012	DODG	CVN	SV	Auto	12/2022	Grand Caravan. Passanger Van Front WD 3.6L 6 Cyl Pwr windows, locks, mirrors AC AM/FM/CD Cruise Control	203626	YES	2C4RDGBG2CR203626	Black	80,842					<b>Mechanical:</b> Check engine light is on, no known issues, van has been sitting for a few months, brakes may be rusty from sitting, the am/fm radio does not work, asking for a code in which we do not have, tires are winter tread with about 25% tread life remaining, replacing due to normal rotation of inventory. <b>Body:</b> Minor scratches throughout, some rust starting on rear liftgate, some rust on the drivers side lower dog leg and side sliding door in front of the rear wheel, headlights are faded/cloudy. <b>Interior:</b> Interior is dirty and in need of cleaning, equipped with stow-n-go fold in the floor seating, rear HVAC controls.
BGS56 FPR8	87 88	2014 2011	CHEV FORD	SLV RNG	CW PK	Auto TRK	02/2023 2/2023	Silverado 2500. 6.0L 8 Cyl, AM/FM/CD PW, PL, PM, cruise, 4WD 2WD; cap	134779 A55554	YES YES	1GC1KVCGXE134779 1FTKR1AD8BPA55554	Brown WHI	153,925 36195					<b>Mechanical:</b> Manifolds leaking, was in use up until about Feb 2023, unknown mechanical issues if any. <b>Body:</b> Body is in poor condition, rust, rot, dents, dings and scratches throughout <b>Interior:</b> interior is in poor shape, seats torn, very dirty, holes from accessory removal
BGS56 FW15	89 90	2015 2016	CHEV CHEV	SLV SLV	4C 4C	TRK TRK	10/2023	Silverado. DRW 3500. 4WD 6.0L 8Cyl AC AM/FM Pwr windows locks Cruise control Toy Package SILVERADO 1500 Extra Cab 4x4	507922 241853	YES YES	1GC5KYCVGFZ507922 1GCVKNEC9GZ241853	Red Green	117,583 UNK					<b>Mechanical:</b> tires are winter tread with approx 75% tread life remaining, equipped with scissor dumping flat bed that is electric over hydraulic in-cab operated, manual 4WD, equipped with Fisher 9'5" extreme V-Plow with fiststick controller, truck was utilized to plow a state airport where salt usage is not allowed due to corrosion properties, last users reported no known mechanical issues, vehicle replaced due to normal replacement planning process, 4.10 rear end gear ratio. <b>Body:</b> Cracked windshield, drivers seat worn, drivers door sill paint rubbed off, whelen roof top lightbar, minor scratches throughout, minor dent in lf fender. <b>Interior:</b> Interior is dirty, drivers seat worn and torn, some holes in the interior from accessory removal, equipped with rubber flooring, back of drivers seat is falling off.
BGS56 AOT10	91 92	2012 2015	FORD CHEV	F25 EXP	CW VN	TRK VAN	4/2023	F250 XL. 4WD 6.2L 8Cyl AC AM/FM Cruise Control Tow package G30 EXPRESS VAN	B08810 250987	YES YES	1FTTW2B61CEB08810 1GCZGUCCG9F1250987	White N/A	47,201 N/A	N/A				<b>Mechanical:</b> Truck does not currently run, no crank, no start, diagnosed by Ford dealer and "found power circuits from the PCM power relay damaged and corroded, needs a new BJB and wire harness", intermittent no start issues leading up to this recent no start issue, truck was being used regularly and last users reported no other known issues or defects, tires are winter tread with about 50% tread life remaining, transmission shift linkage has been disconnected, Equipped with 4.30 electronic locking rear end. <b>Body:</b> Crew cab, long bed, Liftgate is rusted and rotted however is still operational,minor scratches throughout, some rust streaking on paint, mirrors are rusted and rotted at the lower hinge points, lower areas showing some signs of rust, truck equipped with Fieber 2 plug stainless steel 8'6" v-plow, plow is in operational condition. Will need to be towed or trailered, trac-rac and rear window guard may be removed and retained by seller. <b>Interior:</b> Interior is slightly dirty and in need of light cleaning, rubber flooring equipped, drivers seat is a little worn and torn, some holes in interior from accessory removal.
BGS56	93	2014	FORD	F15	CW	Auto	04/2023	F150 XL 4WD. 5.0L 8 cyl. AM/FM/CD PW, PL, PM, cruise, 4WD	G23267	YES	1FTFW1EF9EKG23267	Blue	132,791					Dead, blown engine, needs towing, ODOROUS
BGS56	94	2010	FORD	F15	CM	Auto	05/2023	F150 XL Truck. 4.6L 8 cyl. AM/FM CD, PW, PL, Cruise, 4WD	B65480	YES	1FTEW1E88AFB65480	Red	75,780					<b>Mechanical:</b> Est Repairs for brakes and manifolds \$3,900 not including rust repairs needed, <b>NO BRAKES</b> , front caliper extended and leaking, therfore no brakes, dealership diagnosed it as needed a new front caliper, front and rear brakes and exhaust manifolds <b>Body:</b> Heavy rust and rot throughout <b>Interior:</b> Interior is fair shape for age
BGS56 FW15	95 96	2014 2016	CHEV CHEV	TK SLV	PK 4C	TRK TRK	2/2023 Expired	Silverado. 1500 Ext Cab. 4WD 5.3L 8 Cyl Pwr windows, locks, mirrors AC AM/FM Cruise Control Silverado. 4WD,power windows/locks, AC	227591 241995	YES YES	1GCVKPCE0EZ227591 1GCVKNCE7GZ241995	Green Green	83,565 83,058					<b>Mechanical:</b> Tires are winter tread with less than 25% tread life remaining, intermittent service strabitrak, ABS and traction lights illuminated. Previous operator stated transmission feels like it slips sometimes, dealership diagnosed truck and recommended transmission replacement, due the body condition seller opted not to repair transmission. Truck was driven about 75 miles from dealership back to Fleet location with no transmission issue. <b>Body:</b> Rocker panels and cab corners are in need of repair, heavily rusted and rotted, would not pass state inspection in current condition, under side of truck expected to be just as rusty, truck does have an ARE fiberglass truck cap, truck equipped with spray in bedliner. Headlights have sun fading and light cracking, rust starting to bubble over rear wheel wells, scraped left front bumper, other minor scratches may be found throughout. <b>Interior:</b> Interior is dirty and stained with paint, equipped with rubber interior flooring, PW, PL, PM. ODOROUS
AOT10	98	2012	CHEV	EXP	VN	VAN	8/23	G20 EXPRESS VAN	219605	YES	1GCVKNECX2219605	GRN	76382		N/A			Fair
AOT10	99	2011	CHEV	TK	CW	TRK		SILVERADO 2500	178960	YES	1GC1XXCG9BF178960		161355					Needs batteries, runs and drives, foul interior odor.
AOT10	101	2014	CHEV	TK	PK	TRK		SILVERADO 3500	162283	YES	1GC3KOCG6EF162283		110579					starts and drives, needs muffler, open GM recall
FPR8	102	2011	FORD	TK	PC	TRK	05/23	2WD Ford Ranger	A55556	YES	1FTKR+A71.M711ED9BPA55556	White	73038					Rusty, starts drives, no known defects, no plow controller
FW15	103	2017	CHEV	TK	TRK	1/24		Silverado. Pick-up truck 4x4	219861	YES	1GCVKNEC6H2219861	GRN	93645	N/A				Fair
FPR8	104	2011	CHEV	EXP	EC	AUTO	4/2023	tool r+A21:J22acks, ladder rack on top, 2WD	121737	YES	1GCZGUCA2B121737	GRN	182087					poor--not inspectable, rear frame rotted through; several dashboard lights on (engine, ABS, airbag, tire, traction)
FW19 AOT10	105 106	2014	CHEV	SLV	CW	TRK	2/2023	SILVERADO 4WD, AC, automatic, power doors and locks, radio FRONT PLOW HITCH TENCO	495715	YES NA	3GCUKPEC0EG495715	BLK	118,954					Failed inspection due to corroded rocker panels, middle console removed, minor body damage, tires purchased in 12/2021
FW19	107	2011	CHEV	SLV	PK	TRK	11/23	Silverado. 4WD, A/C, automatic, 5.3L V8, tow hitch platform, AM/FM radio (no CD or tape player), GM adjustable truck rack	384336	YES	1GCNKPE0XBZ384336	GRN	133948					needs oil change, sheet metal denting to right side from passenger compartment to back of bed, rusted cab corners on both sides with one semi-repairs, over the rear wheel wells badly rusted, cruise control doesn't work, small dents and scratches on bed rail, driver's seat fabric torn, ABS light occasionally comes on
AOT10	108	2014	INTL	TK	CB	TRK		INTERNATIONAL TERRA STAR.	042666	YES	1HTKPSKKE6H042666		69513	2792				CEL on, needs batteries, don't drive, needs towing
AOT10	109	2006	INTL	TK	CC	TRK		INTERNATIONAL 7300	344738	YES	1HTWAAAL16J344738		149982	7899				Rusty, runs and drives
AOT10	110	2012	INTL	TK	TK	TRK		INTERNATIONAL 7400	536117	YES	1HTWDAZAR4J536117		74352	4272				Rusty, starts drives, no known defects
AOT10	111	2012	INTL	TK	DP	TRK		INTERNATIONAL 7400	536110	YES	1HTWDAZAR1CJ536110		104574	5759				check transmission light on, yawn drives and runs, fair condition, recommend towing
AOT10	112	2010	INTL	TK	DP	TRK		INTERNATIONAL 7600	266146	YES	1HTWXSHR3AJ266146		93915	4845				need batteries, starts and runs, rust, no leaks.
AOT10	113	2013	INTL	TK	DP	TRK		INTERNATIONAL 7600	203002	YES	1HTGRSHT7DJ203002		76170	3977				rust, starts and runs.
AOT10	114	2015+	CHEVROLET	1500				TAKE OFF BED	NA									New, Take Off
AOT10	115	2022+	CHEVROLET	2500+				66" NEW TAKE OFF BED	NA									New, Take Off
AOT10	116	2022+	CHEVROLET	2500+				66" NEW TAKE OFF BED	NA									New, Take Off
AOT10	117	2015+	CHEVROLET	2500+				8" NEW TAKE OFF BED	NA									New, Take Off
FPR8	118		Kubota	L2250	tractor			includes front bucket model BF400G (SN12162)	NA		Serial number L2250D-50719	orange	880					poor--works in 2WD only, but gears otherwise not working
FPR8	119		Kubota	L35				Kubota L35 tractor with backhoe	NA		135864799	Orange		1758				Fair
AOT81	120		FORD	1700	TRACTOR			1700 TRACTOR	NA		U709377	BLUE		3577				UNKNOWN - comes with a finish mower
FW19	121	1977	Ford	3600	Tractor		N/A	2WD, 48hp, 2.9L 3-cyl.diesel engine, 3-point hitch with 6' back blade	527500	NA	C527500	Blue/White	N/A	2991				front tires have slow leak; body has been touched up with blue paint prior to State ownership; small hydraulic fluid leak; it runs, PTO and hydraulics work, but buyer WILL NEED BATTERY TO START
AOT10	122	2006	CATEPILLAR	924G		LDR		LOADER	A03127	NO	DDA03127		3269					Used, hyd leaks, starts, runs,light linkage, minor rust, does not shift properly in auto
AOT10	123	2008	CATEPILLAR	924H		LDR		LOADER	C00877	NO	CA109244HEHX00877		5899					Used, coolant leak, starts, runs, loose linkage, minor rust.
AOT10	124	2008	CATEPILLAR	924H		LDR		LOADER	C01008	NO	CA109244HHX001008		5755					fuel leaks from primer, add coolant light on, loose linkage, bucket has rusting, rust on unit.
AOT10	125	2000	JOHN DEERE	544H		LDR		LOADER	W57528	NO	DW544HX577528		5755					rusty, starts and runs. Loose pins
AOT10	126	2000	JOHN DEERE	544H		LDR		LOADER	W57512	NO	DW544HX577512		8312					small hydraulics leaks, runs well, starts, rusty
AOT10	127		TENCO			PLOW		11' TWIST N SHOOT PLOW	NA		N/A							Used, Rough Shape

AOT10	128		VIKING			PLOW		11' ONE-WAY PLOW		NA	N/A				Used, Rough Shape
AOT10	129		EVEREST			PLOW		11' POLY FLEX PLOW		NA	N/A				Used, Rough Shape
COR52	130	2013	INTL	TK	VN	TRK	12/2022	25' Box truck. Air Brakes, Diesel ,	151407	YES	1HTMKAZL3DH151407	BLU	199100	N/A	Used. needs hydraulic lift gate work, Needs all tires, Needs Vermont State Inspection, Needs Brakes on Rear axle, needs air canisters on rear axle, Need fuel tank mount straps.
LIQ1	131	2014	FRHT	TK	TR	Truck	expired	Freightliner. 10 Wheel box truck, 22 ' box. Automatic trans, power locks, Air Brakes, Rear door ramp, Roll up rear door, 4 side entry door in box, AM/FM CD Radio	FN6540	YES	1FVHCYCY1EHFN6540	Green / White	207770	1693	Check engine light on, Unknown issue. Good Drive tires, steer tires are thin. Turbo, exhaust system, and several emmissions components replaced in the last year. Brakes and air ride components are all functional. Starts and runs well.
AOT10	132	1971	FRUEHAUF	SS/TANKER		TRL		5,000+ GALLONS	358704	NO	UNK358704				<b>BOS Only</b> , poor condition, brakes need replace, rust all around.
AOT10	133	2000	HILLSBORO	TL	FB	TRL		TRAILER	021398	YES	1TH3B6C5251021398				No know defects, rusty, won't pass inspection
AOT10	134	1993	INTE	TL	FB			Interstate 40DLA trailer	200079	YES	1JKDLA203PA200079				Needs brake work, minor rust, needs deck/ramp repair
AOT10	135	2006	CAMI	TL	SE	TRL		20CAM825TA SUPERLINE	015610	YES	5JPBU31266P015610				Rusty, no know defects
AOT10	136	2001	JOHN DEERE	110		EXC		EXCAVATOR	020262	NO	P00110X020262		7924		Runs and crawls, all functions work, minor leaks, loose pins, includes ditching bucket
AOT10	137	2001	JOHN DEERE	110		EXC		EXCAVATOR	020265	NO	P00110X020265		8524		Runs and crawls, all functions work, minor leaks, loose pins
AOT10	138	2007	CME	55 TRACK DRILL RIG		DRL		DRILL RIG	356675	NO	356675		669		no known defects, starts and runs.
AOT10	139	2002	JOHN DEERE	772CH				Grader	585463	NO	DW772CH585463		3943		starts and runs, all functions work, minor wear.