

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Imp. Exp.	Description	Last 6 digits of VIN #	TITLE	Complete VIN#	Color	Mileage	Hours	Condition	BIDDER #/AMT	LOT#	
PS1	001	2009	CHEV	IMP	4D			Impala, 3.5L engine, 6 cyl, auto, power steering, brakes, doors.	326042	Y	2G1WB57N481280642	Silver	99429		Dent in fender, left front	256	\$4,500.00	001
PS1	002	2009	CHEV	IMP	4D			Impala, 3.5L engine, 6 cyl, auto, power steering, brakes and doors. Police Package	283942	Y	2G1WSS7M001283942	BLACK	101621		NKD	89	\$5,400.00	002
PS1	003	2009	CHEV	IMP	4D			Impala, 3.5L engine, 6 cyl, auto, power steering, brakes and doors. Police Package	283957	Y	2G1WSS7M001283957	Black	113,577		NKD	89	\$4,000.00	003
AOT10	004	2006	CHEV	IMP	4D			IMPALA, ADR, 3.5L GAS V6, AT, FRONT WHEEL DRIVE, A/C, CRUISE, PDL, PW, AMFM-CD, POLICE PACKAGE	367737	Y	2G1WSS1698967737	BLACK	103677		POWER STEERING PUMP IS NOISY	29	\$3,000.00	004
PS1	005	2009	CHEV	MAL	4D			Malibu, 2.4L engine, 4 cyl, auto, power steering, brakes and doors.	244650	Y	1G1ZG57B46244650	Silver	103106		Cracked Manifold, needs brakes.	29	\$4,000.00	005
BGS56	006	2009	DOOD	CVN	WN	AUTO	42015	Grand Caravan, FWD - 3.3L 6 Cyl - Auto Trans. A/C, Cruise Control, PWR windows, mirrors and locks AMFM/CD	664410	Y	2D8R44E6R664410	Tan	81116		Body. Paint bubbling on edges of fill gate and front edge of hood. Right rear wheel cover missing. Small stone chips in windshield. Tires in good condition. Right front end damage, bent subframe. Repair estimate is \$1,397. Mechanical: Check engine light on. Interior: Upholstery lightly stained and worn. There are small holes in "B" pillar trim from divider removal.	59	\$5,900.00	006
BGS56	007	2010	DOOD	CVN	SV	AUTO	82015	Grand Caravan, FWD - 3.8L 6 Cyl - Auto Trans. Cruise Control, A/C, AMFM/CD Power locks, windows and mirrors	366695	Y	2D8R3D310AR366695	GOLD	101,415	101422	Body: Scrape on left rear bumper. Hair damage on hood and roof. Small stone chips in windshield. Tires in good condition. Mechanical: Vehicle in poor running condition. Interior: Upholstery is lightly stained and worn.	111	\$4,500.00	007
LQ1	008	2006	FORD	FRE	SV		expired	Freestar mini van, front wheel drive, automatic, seven passenger, electric locks and windows.	A50607	Y	2FJMZ51616SA050607	SILVER	124419		Shifter selector is stiff needs repair. Runs good. Has been sitting for 6 months.	263	\$1,700.00	008
PS1	009	2009	CHEV	IMP	4D			Impala, 3.5L engine, 6 cyl, auto, power steering, brakes and doors. Police Package	316365	Y	2G1WSS7M191316365	Black	100,435		NKD	88	\$3,700.00	009
PS1	010	2009	CHEV	IMP	4D			Impala, 3.5L engine, 6 cyl, auto, power steering, brakes and doors. Police Package	283577	Y	2G1WSS7M39283577	Black	132,056		Body damage, right front	263	\$3,700.00	010
PS1	011	2011	FORD	FJUS	4D			Malibu, 2.5L engine, 4 cyl, auto, power steering, brakes and doors.	243601	Y	2FAB7P2A28R243601	White	140160		RR window lift, RR body damage, windshield chipped.	20	\$3,100.00	011
PS1	012	2007	CHEV	MAL	4D			Malibu, 3.5L engine, 6 cyl, auto, power steering, brakes, doors.	241137	Y	1G1ZT58N87241137	Gold	103658		NKD	265	\$3,000.00	012
PS1	013	2011	FORD	CVC	4D			Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	144412	Y	2FAB7P7V8X144412	Green	89361		Bad Transmission, Exh. Manifold leak, rear brakes low, torn rear bumper cover.	130	\$4,000.00	013
PS1	014	2010	FORD	CVC	4D			Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	119391	Y	2FAB7P7V4X119391	Green	120177		Lift, dirt, air bag light.	49	\$2,800.00	014
PS1	015	2010	FORD	CVC	4D			Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	119391	Y	2FAB7P7V4X119391	Green	117717		Rear Differential leak, air bag light, exh leak.	49	\$3,000.00	015
PS1	016	2010	FORD	CVC	4D			Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	129972	Y	2FAB7P7V4X129972	Green	103764		Rear Axle issue.	139	\$2,900.00	016
PS1	017	2007	CHEV	MAL	4D			Malibu, 2.5L engine, 4 cyl, auto, power steering, brakes, doors.	247148	Y	1G1ZT58P97247148	Silver	72,380		Missing hub cap, stained seats, check engine light on.	212	\$3,250.00	017
PS1	018	2009	FORD	CVC	4D			Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	102297	Y	2FAB7P7V19X102297	Green	124744		NKD	49	\$2,200.00	018
PS1	019	2010	FORD	CVC	4D			Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	119405	Y	2FAB7P7V7A119405	Green	117852		Broken manifold stud	49	\$2,850.00	019
PS1	020	2010	FORD	CVC	4D			Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	129964	Y	2FAB7P7V4X129964	Green	112162		NKD	139	\$3,200.00	020
FPR8	021	unk	Grumman	canoe				Canoe 17 ft. 5 person	GBM79725M79K7A						Good - fair, has been in storage for an extended time -likely taken out of service due to small leak in keel	18	\$175.00	021
FPR8	022	unk	Michcraft	canoe				Canoe 17 ft. 5 person	MEY71022B000						Good - fair, has been in storage for an extended time -likely taken out of service due to small leak in keel	238	\$175.00	022
FPR8	023	unk	Grumman	canoe				Canoe 17 ft. 5 person	GBM79755M79K7A						Good - fair, has been in storage for an extended time -likely taken out of service due to small leak in keel	221	\$200.00	023
FPR8	024	2010	Perception	Acadia II 14.0	kayak			Kayak tandem	WEMDQXBKE010			Yellow			FAIR - needs replacement seats which can be found online, has slight leak from repaired hull. fair- has been in storage for extended amount of time - likely was taken out of service due to small leak in keel area	18	\$275.00	024
FPR8	025	unk	Grumman	V1457	row boat			Boat - 4 person aluminum row	0MCS8686E393						fair- has been in storage for extended amount of time - likely was taken out of service due to small leak in keel area	134	\$300.00	025
FPR8	026	unk	Sea Nymph	V1457	row boat			Boat - 4 person aluminum row	0MCS9222C595						fair - has been in storage for an extended amount of time - likely was taken out of service due to small leak in keel area	349	\$375.00	026
FPR8	027	unk	Sea Nymph	V1457	row boat			Boat - 4 person aluminum row	0MCS3513F595						fair- has been in storage for extended amount of time - likely was taken out of service due to small leak in keel area	307	\$375.00	027
AOT10	028							Boat, aluminum 14R Sea Nymph, 1984 GATO TRAILER AND 7.5 HP MERCURY ENGINE							BOAT HOLDS WATER, TRAILER TIRES ARE FLAT	267	\$775.00	028
FPR8	029	unk	Starcraft	SL-12 7	row boat			Boat - 3 person aluminum row	STRP5004C585						fair - has been in storage for an extended amount of time - hole in bottom has been repaired - easily taken out of service due to leak	22	\$325.00	029
FPR8	030	unk	Starcraft	SL-12 7	row boat			Boat - 3 person aluminum row	STRP5008C585						fair - has been in storage for an extended amount of time - likely was taken out of service due to small leak in keel area	334	\$625.00	030
FW15	031	2000	Polaris	Touring	n/a			Snowmobile - 2 up, 550 CC	KAAS15858C004043		Blue	2059		mirrors broken off, front bumper dent, seat torn & laped, starts and runs	349	\$600.00	031	
FW15	032	2001	Polaris	Legend	n/a			Snowmobile - 4 stroke 1000cc	3BP529234XV00018		Black	1331		Good	277	\$175.00	032	
FW15	033	2007	John Deere	X540				Mower - 54", 26hp 4 cycle, liquid-cooled engine, variable speed hydrostatic transmission.	MOX540021394		green	333		decent shape	328	\$4,400.00	033	
BGS56	034							Cap A.R.E. from 2013 Ford F150 Crew cab							new custom aluminum cover- never used	328	\$125.00	034
FPR8	035							Reservoir cover - Aluminum (custom made)- approx 4ft x 4ft square - 2" high, 2 handles on top for removal							was in storage - tank ok - in good condition missing portion of hand pump	17	\$80.00	035
FPR8	036							Fuel tank - Older portable - 30 gal +/- with hand crank pump							was in storage - tank ok - in good condition missing portion of hand pump	323	\$5.00	036
FPR8	037							Mower, antique manual push mower with wooden handle and cast wheels							ok - in storage mower in good condition one cast wheel has broken hub	15	\$130.00	037
FPR8	038							Ladder, foldable aluminum, type 1A extra heavy duty industrial, 14ft fully extended, 7ft step ladder, 5ft scaffolding							like new good condition - no known problems - just isn't used	309	\$225.00	038
FPR8	039	2002	Husqvarna	325L	Trimmer			Trimmer, string - 6 each, 2002 Husqvarna 325L, 2004 Husqvarna 322L, 2001 Husqvarna 325L, 1998 Husqvarna 232R, 1997 Husqvarna 232R, 1998 Husqvarna 232R	004100888						fair - runs ok - older model time for upgrade	18	\$125.00	039
FPR8	040	unk	Kay Park	Pedal Cruiser	pedal boat			Boat Pedal	KAX0556T000		RED				FAIR - Worked when removed from service, some hull wear & tear damage	18	\$250.00	040
FPR8	041	unk	Kay Park	Pedal Cruiser	pedal boat			Boat Pedal	KAX0556J000		BLUE				FAIR - Worked when removed from service, some hull wear & tear damage	338	\$50.00	041
FPR8	042	unk	Kay Park	Pedal Cruiser	pedal boat			Boat Pedal	KAX0557J000		GREEN				FAIR - Worked when removed from service, some hull wear & tear damage	131	\$50.00	042
FPR8	043	unk	Kay Park	Pedal Cruiser	pedal boat			Boat Pedal	KAX0556H000		Yellow				FAIR - Worked when removed from service, some hull wear & tear damage	304	\$75.00	043
FPR8	044	unk	Kay Park	Pedal Cruiser	pedal boat			Boat Pedal	KAX0468F000		BLUE				FAIR - Worked when removed from service, some hull wear & tear damage	87	\$75.00	044
FPR8	045	unk	Kay Park	Pedal Cruiser	pedal boat			Boat Pedal	KAX0426H095		Yellow				FAIR - Worked when removed from service, some hull wear & tear damage	270	\$75.00	045
FPR8	046	2003	Kawasaki	Mule 3000 - KAF620	Utility Vehicle			Utility vehicle - 2WD, 2 person, 1330lb load capacity, 1200 lb tow capacity, Automatic w/ forward & reverse, locking differential, gas, 617cc engine, tilt cargo bed	KJ1KAF02138505570		green	1403			good condition, used unit taken out of service. Serviced annually since purchase. Starts hard (must use choke) low idle leads to stalling. This is typical of this model Mule	259	\$3,100.00	046
FPR8	047		Kawasaki	Mule 3000 - KAF620	Utility Vehicle			Utility vehicle - 2WD, 2 person, 1330lb load capacity, 1200 lb tow capacity, Automatic w/ forward & reverse, locking differential, gas, 617cc engine, tilt cargo bed	KJ1KAF02138505794		green	1811			good condition, used unit taken out of service. Serviced annually since purchase. Starts hard (must use choke) low idle leads to stalling. This is typical of this model Mule	282	\$3,100.00	047
FPR8	048	2003	Kawasaki	Mule 3000 - KAF620	Utility Vehicle			Utility vehicle - 2WD, 2 person, 1330lb load capacity, 1200 lb tow capacity, Automatic w/ forward & reverse, locking differential, gas, 617cc engine, tilt cargo bed	KJ1KAF02138505710		green	2405			good condition, used unit taken out of service. Serviced annually since purchase. Starts hard (must use choke) low idle leads to stalling. This is typical of this model Mule	218	\$2,800.00	048
AOT10	049		MOUNTAIN	MTN5590				LIFT - 10,000 POUND TWO POST AUTOMOTIVE, 230 VOLTS, SINGLE PHASE, 20 AMP	09080000002814		RED				NO KNOWN DEFECTS	101	\$1,000.00	049
AOT10	050		MOUNTAIN	MTN5590				LIFT - 10,000 POUND TWO POST AUTOMOTIVE, 230 VOLTS, SINGLE PHASE, 20 AMP	09080000002813		RED				NO KNOWN DEFECTS	140	\$1,000.00	050
AOT10	051							FLOATING DRILLING RIFT WITH BOAT, HOME MADE - BARELLS ARE FOAM FILLED				BLACK/BLUE			HAS NOT BEEN USED FOR A LONG TIME. ANY DEFECTS UNKNOWN	101	\$400.00	051
AOT10	052							BED CHAIN - LAROCHELLE							UNUSED CONDITION	68	\$100.00	052
AOT10	053		LINCOLN	AC 250				WELDER - LINCOLN IDEALARC 250	AC - 224398		RED				HAS NOT BEEN USED FOR A LONG TIME. ANY DEFECTS UNKNOWN	243	\$60.00	053
AOT10	054		Miller					Welder, Miller							Unknown	85	\$50.00	054
AOT10	055							MISCELLANEOUS PARTS (BOX), MANY NEW, MOST FOR INTERNATIONAL							NO KNOWN DEFECTS	39	\$80.00	055
AOT10	056							HAND PUMPS (BOX) FOR 55 GALLON BARELLS, HOMELETTE CHAINSAW							DEFECTS UNKNOWN	29	\$60.00	056
AOT10	057							DOLLIES - 5 EACH							DEFECTS UNKNOWN	166	\$20.00	057
AOT10	058							JACK - TRANSMISSION - 2							WORKING CONDITION, DEFECTS UNKNOWN	96	\$470.00	058
AOT10	059							JACK - 10 TON AIR OVER HYDRAULIC							AIR/HYDRAULIC LEAK	162	\$170.00	059
AOT10	060		MARQUETTE	W93962				JACK - 10 TON AIR OVER HYDRAULIC							AIR LEAK	283	\$175.00	060
AOT10	061		MARQUETTE	W93962				JACK - 10 TON AIR OVER HYDRAULIC							AIR LEAK	283	\$300.00	061
AOT10	062							JACK STANDS - 4 - FOR TWO POST LIFT							NO KNOWN DEFECTS	80	\$250.00	062
FPR8	063		Bosch	18V				Tool Kit Bosch 18V - includes skill saw, sawzall, 1/2" drill-driver, charger and two batteries. Misc cordless 18v includes: 1/2" drill-driver, 1/2" hammer drill, sawzall, nail saw, and flashlight							good condition - tools work fine - batteries don't hold charge for extended periods of time	121	\$200.00	063
FPR8	064		MSA Otton					Multigas detector battery operated and misc attachments							Due to age needs gas sensors replaced and calibration in order to operate unit	205	\$25.00	064
BGS56</																		

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	TITLE	Complete VIN#	Color	Mileage	Hours	Condition	BIDDER #	AMT	LOT#							
BGS56	094							Tires - 31 - 2-Champiro WT-65 185/65R15, used 9/32" tread, date code 2507 - 1-plugged, 3-Goodyear Integrity 185/65R15, used 7/32" tread, date code 4708 - 3-Champiro WT-60 195/65R15, used 9/32" tread, date code 2408 - 3-Hankook Optimo 195/65R15, used 5/32" tread, date code 5109 - 2-Wintermark MagnaGrip 195/65R15, used 9/32" tread, date code 2307 - 1-Galvalud NordFrost 195/65R15, used 4/32" tread, date code 2609 - 1-Firestone FR380 195/65R15, used 11/32" tread, date code 3507 - 3-Toyo Extensa AS 195/65R15, used 7/32" tread, date code 0109 - 2-Continental Touring Contact AS 215/65R16, used 9/32" tread, date code 0800 - 1-Cooper WeatherMaster S12 225/60R17, used 9/32" tread, date code 2409 - 3-Michelin Latitude Tour 235/70R16, used 5/32" tread, date code 0109 - 1-Cooper Discoverer HIT 235/65R16, used 11/32" tread, date code 1006 - 3-Bridgestone Viteal Ribbed 265 245/75R16, used 7/32" tread, date code 3608 - 2-Goodrich Rugged Trail TA L1245, date code 1006 - 7/32" tread, date code 1708 - 1-Goodyear Workhorse L1245/75R16, new, date code 2204.																	
PS1	095	2010	FORD	CVC	4D	Auto		Crown Victoria, 4.6L engine, 8 cyl, auto, power steering, brakes and doors.	129955		2FABP7BV4AX129955	Green	98304		Accident Damage, front wheel/fender.	139	\$2,750.00	095							
NS742	096	2008	FORD	CVC	4D	Auto	Expired	Crown Victoria, Police Interceptor	123763		2FAP7P1V18X123763	White	132541		Fair	49	\$950.00	096							
PS1	097	2010	CHEV	MAL	4D	Auto		Malibu, 2.4L engine, 4 cyl, auto, power steering, brakes and doors.	183338		1G1ZSEB2AF183338	Silver	71M1		Included in accident, salvage title.			097							
FPK8	098	2000	CHEV	SLV	PK	Auto	June 2015	Silverado, 4.8L automatic transmission	389118		1GCEC14V3E2389118	Green	87986		body in poor condition, service engine light is on, exhaust leak, runs decent	220	\$1,900.00	098							
AOT10	099	2008	CHEV	SLV	CW	TRK		SILVERADO 2500HD, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	214767		1GCHK2K18F214767	BLUE	150525		CHECK ENGINE LIGHT IS ON, BRAKES ARE BAD - PEDAL IS LOW, NOISES IN FRONT END, DO NOT DRIVE	118	\$9,000.00	099							
AOT10	100	2008	CHEV	SLV	CW	TRK		SILVERADO 2500, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD, DUAL BATTERIES	212362		1GCHK2K98F212362	BLUE	188915		SURFACE RUST, MOLDING IS COMING OFF DRIVERS DOOR	49	\$7,300.00	100							
PS1	101	2005	CHEV	TK	4C	Auto		Silverado 1500 Ext cab, 4.8L engine, 8 cyl, auto, power steering, brakes and doors.	190124		1GCEK19V25E190124	Blue	150077		Cracked windshield, body rust	49	\$4,300.00	101							
PS1	102	2007	CHEV	SLV	4C	Auto		Silverado 1500 Ext cab, 4.8L engine, 8 cyl, auto, power steering, brakes and doors.	122165		2GCEK19V07122165	Green	100,243		Check engine light, rear end leak, tailgate latch frozen.	189	\$5,300.00	102							
AOT10	103	2008	CHEV	SLV	CW	TRK		SILVERADO 1500, 4DR CREW CAB, 4WD, 5.3L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	267203		2GCEK2386E267203	BLACK	164695		NO KNOWN DEFECTS	118	\$8,900.00	103							
AOT10	104	2007	CHEV	SLV	CW	TRK		SILVERADO 1500, 4DR CREW CAB, 2WD, 4.8L GAS V8, A/T, A/C, CRUISE	647428		2GCEC13C671647428	BLACK	143275		UPPER AND LOWER BALL JOINTS LOOSE ON LEFT SIDE, TPMS LIGHT IS ON, RIGHT FRONT WHEEL BEARING IS LOOSE	118	\$6,200.00	104							
PS1	105	2009	CHEV	TK	4C	Auto		Silverado, 1500 Ext cab, 4.8L engine, 8 cyl, auto, power steering, brakes and doors.	258055		1GCEK19C39E258055	Green	122367		Cracked windshield, flat tires	118	\$9,100.00	105							
FPK8	106	2007	CHEV	SLV	PK	Auto	April 2014	Silverado 3500, 4wd, reg cab, with rack dump body and 8 HD Fisher plow.	156978		1GBHK4JX7E156978	GREEN	35859		Very good condition. Body excellent. No known problems with truck. Dump body does not raise. Believe it is a minor electrical issue with the hyd pump.	167	\$12,000.00	106							
AOT10	107	2004	CHEV	SLV	4C	TRK		SILVERADO 2500, 4DR EXTEND CAB, 4WD, 6.6L DIESEL V8, A/T, A/C, CRUISE, DUAL BATTERIES	355695		1GCHK2926A6355695	BLUE	201045		CRACK IN WINDSHIELD, LOOSE PITMAN ARM AND IDLER ARM, RIGHT HEADLIGHT IS BROKEN, CHECK ENGINE LIGHT IS ON	58	\$4,000.00	107							
FW12	108	2001	DODG	TK	CC	TRK	8/2015	Dodge, 4WD, 3500 Flat Bed truck with 9' Fisher Plow	531848		3B8MF36571M531848	GRN	61247	NA	Runs, Drives, Stops. 4 Wheel drive works. Plow works, rusty, Broken Dash, needs gas tank straps, noisy belt	58	\$4,000.00	108							
AOT10	109	2006	CHEV	SLV	CW	TRK		SILVERADO 3500, 4DR, 4WD, 6.6L DIESEL V8, A/T, A/C, CRUISE, DUAL BATTERIES, UTILITY BODY	192190		1GCHK3D06F192190	BLUE	143544		Only noted possible defect is that when driven in traffic at certain slower speeds, the transmission sometimes shifts or surges between drive and the next lower gear. This does not happen all the time.	49	\$8,800.00	109							
FPK8	110	2000	CHEV	TK	PK	TRK	4/30/2016	S10, Automatic, 2WD Tool boxes - 2 side boxes	243529		1GCCS1453YK243529	GRN	131502		LOW IN BENT, LEFT INNER TIE ROD IS LOOSE, TPMS LIGHT IS ON	317	\$2,100.00	110							
AOT10	111	2009	CHEV	SLV	CW	TRK		SILVERADO 2500HD, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	214288		1GCHK2K38F214288	BLUE	134337		RIGHT UPPER BALL JOINT IS LOOSE, LEFT MANIFOLD IS LEAKING, BROKEN MIRROR ON RT SIDE, NEEDS TIRES, LT FRT DOOR HINGES ARE WORN	118	\$12,000.00	111							
AOT10	112	2009	CHEV	SLV	CW	TRK		SILVERADO 2500, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	181398		1GCHK5K19F181398	BLUE	146441		RIGHT INNER TIE ROD AND LEFT OUTER TIE ROD ARE LOOSE, PITMAN AND IDLER ARM ARE LOOSE	301	\$1,800.00	112							
AOT10	113	2008	CHEV	SLV	CW	TRK		SILVERADO 2500, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD, DUAL BATTERIES	214777		1GCHK2K348F214777	BLUE	110878		RIGHT INNER TIE ROD AND LEFT OUTER TIE ROD ARE LOOSE, PITMAN AND IDLER ARM ARE LOOSE	118	\$14,000.00	113							
AOT10	114	2008	CHEV	SLV	4C	TRK		SILVERADO 2500, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD, DUAL BATTERIES	211034		1GCHK2K28E211034	BLUE	154415		CHECK ENGINE LIGHT IS ON, IDLER AND PITMAN ARMS LOOSE	327	\$10,000.00	114							
AOT10	115	2008	CHEV	SLV	4C	TRK		SILVERADO 2500 HD, 4DR EXTENDED CAB, 2WD, 6.6L DIESEL V8, ALLISON AT, A/C, CRUISE, DUAL BATTERIES	204716		1GCHK2SDX6E204716	GREEN	198666		CHECK ENGINE LIGHT IS ON, PITMAN AND IDLER ARMS ARE LOOSE, WINDSHIELD CHIPS, CAP DOOR HINGES NEED REPLACING	49	\$5,000.00	115							
AOT10	116	2008	CHEV	SLV	CW	TRK		SILVERADO 1500, 4DR CREW CAB, 4WD, 5.3L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	280976		2GCEK1338E280976	BLUE	101037		SMALL DENT IN LEFT FRONT FENDER	118	\$12,600.00	116							
BGS56	117	2011	FORD	F15	PK	TRK	4/2015	F150 Reg Cab, 4WD - 5.0L V8 - Auto Trans AMFM, Cruise Control, A/C, w/Cap	D53009		1FTMF1EF2K0D53009	RED	106244		Body: Light hail damage on hood. Rust on right rear bumper edge. Small stone chips on hood and in windshield. Tires are in good condition. Mechanical: Engine seems mechanically sound with no known defects. Interior: Moderately stained. Holes in seat upholstery and screw hole in dash.	10	\$9,800.00	117							
BGS56	118	2007	FORD	TK	PK	TRK	08/2015	F150 Reg Cab, 4WD - 5.4L V8 - Auto Trans, Cruise Control, A/C, AMFM	A29401		1FTYF1450TNA29401	GREEN	65,903		Body: Scratches on hood and sides of vehicle. Rust starting to form in rear wheel wells. Tailgate top cover is missing. Multiple dents and paint stains. Paint stains on rear window and molding, scratches and paint stains in bed. Tires in fair condition. Mechanical: Engine seems mechanically sound with no known defects. Interior: Upholstery somewhat stained and worn, seat is driver's seat.	338	\$8,100.00	118							
FPK8	119	2003	FORD	F25	PK	TRK	2/28/2016	F250, Automatic, 2WD, Tool boxes - 1 Crossbox and 1 side box	A31930		1FTNF20L3EA31930	GRN	172781		No known defects.	98	\$2,500.00	119							
AOT10	120	2006	CHEV	SLV	CW	TRK		SILVERADO 3500, 4DR, 4WD, 6.6L DIESEL V8, A/T, A/C, CRUISE, DUAL BATTERIES, FLAT BED WITH STAKE POCKETS	190354		1GCHK3D06F190354	BLUE	133210		CHECK ENGINE LIGHT IS ON, BRAKE PEDAL IS SOFT AND LOW, NOISE IN FRONT IN 4 WHEEL DRIVE, IDLER ARM, PITMAN ARM AND LEFT INNER TIE ROD ARE LOOSE, BODY IS IN BAD SHAPE - RUSTY, BENT, ENGINE OIL TRANSMISSION COOLER LINES LEAKING, RT FRT AXLE SEAL LEAKING, NEEDS FRONT BRAKES, COOLANT LEAK ON INTAKE MANIFOLD, FRONT U JOINT NOISEY ON DRIVE SHAFT	118	\$11,800.00	120							
AOT10	121	2008	CHEV	SLV	4C	TRK		SILVERADO 1500, 4DR EXTENDED CAB, 4WD, 5.3L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	234173		1GCEK1904Z234173	BLACK	87637		NO KNOWN DEFECTS	60	\$10,900.00	121							
AOT10	122	2007	CHEV	SLV	CW	TRK		SILVERADO 2500 HD, 4DR EXTENDED CAB, 4WD, 6.0L GAS V8, A/T, A/C, AMFM, CAP	151792		1GCHK29U6E151792	BLUE	91803		NO KNOWN DEFECTS	267	\$12,900.00	122							
AOT10	123	2008	CHEV	SLV	CW	TRK		SILVERADO 2500HD, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	214718		1GCHK2K38F214718	BLUE	109378		CHECK TPMS LIGHT IS ON, TAIL GATE IS DENTED	267	\$12,900.00	123							
AOT10	124	2007	CHEV	TK	PK	TRK		SILVERADO 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD, DUAL BATTERIES	537933		1GCHK2K30F537933	BLACK	129962		HOLES IN FLOOR MAT	29	\$11,700.00	124							
AOT10	125	2008	CHEV	SLV	4C	TRK		SILVERADO 2500, 4DR EXTENDED CAB, 2WD, 5.3L GAS V8, A/T, A/C, CRUISE	211237		1GCHK29K9E211237	BLUE	95701		NO KNOWN DEFECTS	101	\$10,500.00	125							
FW15	126	2007	CHEV	SLV	4C	TRK	8/15	Silverado 2500HD, 4WD, AC	138690		1GCHK29JX7E138690	GRN	147114		windshield cracked, surface rust, need tires	29	\$4,400.00	126							
NS42	127	2007	CHEV	TK	PK	TRK	10/15	1950 reg cab, 444, 4.8L V-8, ac, locking rear diff, low hitch, contractors cap	162407		1GCHK14V2E162407	green	123,105		body	49	\$4,000.00	127							
FW15	128	2008	CHEV	SLV	4C	Auto		Silverado, 2500, 4WD	202320		1GCHK2K38E202320	Green	110154		rear window cracked, surface rust, need tires	118	\$8,700.00	128							
PS1	129	2008	CHEV	TK	4C	Auto		Silverado, 1500 Ext cab, 4.8L engine, 8 cyl, auto, power steering, brakes and doors.	247282		1GCEK19C5E247282	Green	94123		NKD.	49	\$8,200.00	129							
AOT10	130	2008	CHEV	SLV	PK	TRK		SILVERADO 2500HD, 2DR REGULAR CAB, 4WD, 6.0L GAS V8, A/T, A/C, AMFM-CD, CAP	211096		1GCHK2K43E211096	BLUE	98527		NO KNOWN DEFECTS	230	\$17,500.00	130							
AOT10	131	2007	CHEV	SLV	CW	TRK		SILVERADO 2500, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	137195		1GCHK23U7E137195	BLUE	152960		NO KNOWN DEFECTS	118	\$8,300.00	131							
AOT10	132	2008	CHEV	SLV	4C	TRK		SILVERADO 1500, 4DR EXTENDED CAB, 4WD, 5.3L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD	234288		1GCEK190XZ234288	BLACK	86439		LEFT EXHAUST MANIFOLD BOLT BROKEN, TRANSMISSION COOLER LINES LEAKING	338	\$1,800.00	132							
AOT10	133	2007	CHEV	SLV	CW	TRK		SILVERADO 2500, 4DR CREW CAB, 4WD, 6.0L GAS V8, A/T, A/C, CRUISE, PDL, PW, AMFM-CD, DUAL BATTERIES	197539		1GCHK29U7E197539	BLACK	150970		SMALL DOORS ON CAP DON'T LATCH OR STAY UP	19	\$7,800.00	133							
PS1	134	2007	CHEV	TK	4C	TRK		Silverado, 1500 Ext cab, 4.8L engine, 8 cyl, auto, power steering, brakes and doors.	590943		1GCEK19C87590943	RED	134677		NKD.	170	\$8,900.00	134							
FW15	135	2007	CHEV	TK	4C	TRK		Silverado, 1500 Ext cab, 4.8L engine, 8 cyl, auto, power steering, brakes and doors.	590619		1GCEK19C87590619	RED	135674		check engine light	100	\$9,200.00	135							
FW15	136	2008	CHEV	SLV	4C	TRK	08/15	Silverado, 2500, 4WD	202709		1GCHK2K38E202709	Green	145806		door	117	\$8,200.00	136							
FW15	137	2008	CHEV	SLV	4C	TRK		Silverado, 2500, 4WD	202415		1GCHK29K2E202415	Green	159811		door	118	\$9,000.00	137							
AOT10	138	2001	INTL	TK	CC	TRK		INTERNATIONAL 2574, CAT C10 6CYL DIESEL, EATON FULLER 9 SPEED MANUAL TRANSMISSION	404011		1HTGGAT7R1404011	ORANGE	137562	753	RUSTY HOLES IN CAB, NO BRAKE LIGHTS, DUMP BODY RUSTY	68	\$8,500.00	138							
AOT10	139	2005	INTL	TK	DP	TRK		INTERNATIONAL 7600, CUMMINS ISM 6CYL DIESEL, FULLER 10 SPEED AUTOSHIFT TRANSMISSION, A/C, CRUISE P.W, PDL, AMFM-CD	154247		1HTVXAHR65154247	ORANGE	119733	6721	NEEDS BED CHAIN, HYDRAULIC LEAKS, CAB SHOCK IS BAD, ENGINE FRONT COVER IS LEAKING OIL, SNOW VALVE IS NOT WORKING, COOLANT RESERVOIR AND OIL PAN LEAK	348	\$29,500.00	139							
AOT10	140	2005	INTL	TK	DP	TRK		INTERNATIONAL 7600, CUMMINS ISM 6CYL DIESEL, FULLER 10 SPEED AUTOSHIFT TRANSMISSION, A/C, CRUISE P.W, PDL, AMFM-CD	030318		1HTVXAHRX5030318	ORANGE	126768	6661	BATTERY BOX COVER IS BROKEN, NO PARKING LIGHTS ON PLOW FRAME	68	\$33,000.00	140							
AOT10	141	2005	INTL	TK	DP	TRK		INTERNATIONAL 7600, CUMMINS ISM 6CYL DIESEL, FULLER 10 SPEED AUTOSHIFT TRANSMISSION, A/C, CRUISE P.W, PDL, AMFM-CD	030319		1HTVXAHR15030319	ORANGE	141095		ENGINE OIL LEAK ON FRONT COVER, SMALL HYDRAULIC LEAKS, NEEDS DRINGS ON FUEL INJECTOR WIRE HARNESS, HAS SOME LIGHTS OUT	68	\$35,000.00	141							
AOT10	142	2005	INTL	TK	CB	TRK		INTERNATIONAL 7400, INTERNATIONAL 530 6CYL DIESEL, ALLISON 3000 SERIES AUTOMATIC TRANSMISSION, A/C, CRUISE P.W, PDL, AMFM-CD	029320		1HTWDADR55029320	ORANGE	100237	5515	POWER STEERING FLUID LEAK, ENGINE OIL LEAK, HYDRAULIC CYLINDERS LEAKING, NEEDS TARP, RIGHT INNER FENDER BRACKET IS RUSTED	77	\$11,000.00	142							
AOT10	143	2005	INTL	TK	CB	TRK		INTERNATIONAL 7400, INTERNATIONAL 530 6CYL DIESEL, EATON FULLER 10 SPEED MANUAL TRANSMISSION, A/C, CRUISE P.W, PDL, AMFM-CD	029343		1HTWDADR65029343														

Division	LOT#	Year	Make	Model	Body	AUTO/TRK	Insp. Exp.	Description	Last 6 digits of VIN #	TITLE	Complete VIN#	Color	Mileage	Hours	Condition	BIDDER #	AMT	LOT#
AOT10	158	2005	INTL	TK	CB	TRK		INTERNATIONAL 4400, INTERNATIONAL DT 466 6 CYLINDER DIESEL, ALLISON 3000 SERIES AUTOMATIC TRANSMISSION, A/C, CRUISE, AIR BRAKES - BOOM TRUCK	888433	Y	1HTMKAAN65H688433	ORANGE	178201	7068	REAR BODY IS RUSTED, LIFT WAS FUNCTIONING - HAS NOT BEEN USED OR INSPECTED IN A YEAR	327	\$9,500.00	158
AOT10	159	2001	INTL	TK	DP	TRK		INTERNATIONAL 4700, INTERNATIONAL DT 466 6 CYL DIESEL, EATON FULLER 6 SPEED MANUAL TRANSMISSION - FLAT BED	339600	Y	1HTSCAAL11H339600	ORANGE	119298	4573	MUFFLER RUSTED OUT	57	\$5,500.00	159
FW12	160	1999	INTL	TK	ST	TRK	4/11	International 4700 Platform truck. Good condition, hasn't been started for a year (NO KNOWN ISSUES AT TIME PARKED) - FLAT BED	591109	Y	1HTSCABM9XH591109	Green	82,470		Good	83	\$6,000.00	160
AOT10	161	2005	INTL	TK	DP	TRK		INTERNATIONAL 7400, INTERNATIONAL DT 466 6CYL DIESEL, ALLISON 3000 SERIES AUTOMATIC TRANSMISSION, A/C, CRUISE P.W. PDL AMFM-CD	158731	Y	1HTWDAAR75J158731	ORANGE	155490	7358	INTERMITTENT HARD START, SKIPS ON START UP AND SMOKES BLACK, LACKS POWER, BROKEN LEAVES IN REAR SPRINGS	216	\$16,250.00	161
AOT10	162	2005	INTL	TK	CB	TRK		INTERNATIONAL 7400, INTERNATIONAL S30 6CYL DIESEL, EATON FULLER 10 SPEED MANUAL TRANSMISSION, A/C, CRUISE P.W. PDL AMFM-CD	029326	Y	1HTWDADR65J029326	ORANGE	133082	6143	SKIPS ON START UP, HYDRAULIC PUMP IS LEAKING, HOLE IN HOOD, EXHAUST LEAK, IRR IS LEAKING, COOLANT LEAK, PANTLE HOOK IS RUSTED IN PLACE, KING PIN SEALS ARE ROTTED, OIL IN AIR SYSTEM	113	\$11,000.00	162
AOT10	163	2003	INTL	TK	DP	TRK		INTERNATIONAL 7600, CAT C10 6CYL DIESEL, EATON FULLER 10 SPEED MANUAL TRANSMISSION, A/C, CRUISE P.W. PDL AMFM	064325	Y	1HTWXAATR63J064325	ORANGE	167799	8651	COOLANT LEAKING INTO OIL PAN, RT FRT MAIN LEAF SPRING IS BROKEN, SOME LIGHTS ARE OUT	113	\$19,500.00	163
AOT10	164	2003	INTL	TK	DP	TRK		INTERNATIONAL 7400, INTERNATIONAL S30 6CYL DIESEL, ALLISON 3000 SERIES AUTOMATIC TRANSMISSION, A/C, CRUISE P.W. PDL AMFM	063851	Y	1HTWDADR13J063851	ORANGE	160821	7562	COMBUSTION GASSES BLOWING BY INTO ENGINE CRANKCASE, HAS NEW FRONT COVER AND CYLINDER KIT IN #1 CYLINDER	34	\$12,500.00	164
TOTAL																\$899,165.00		